



Legendary Automotive Courtesy
Inspection
LEGENDARY AUTO
(239) 277-1004

Robin Cute
1990 Mazda MX-5 Miata
VIN: JM1NA3517L0109761
 118705 mi

Vehicle Health Rating



Pre test drive

Speedometer



Odometer



Dash warning Light or lights on




Learn More

Test Drive

Suspension // Handling

Check every 6 months or 6000 mi



Steering System Operation



Horn





Underhood

Air Filter



Battery



Learn More

Brake Fluid



Recommendation: Brake fluid has exceeded the moisture amount allowed, NEED TO FLUSH BRAKE SYSTEM NOW



Learn More

Power Steering Fluid



Learn More

Engine Oil



Engine Coolant



Learn More

Transmission Fluid



Recommendation: manual trans fluid change



[Learn More](#)

Washer Fluid



Factory Scheduled Maintenance



Inspect Radiator & Hoses

Check every 3 months



Drive Belts And Tensioners



[Learn More](#)

Fluid Leaks



Strut Mounts



UnderCar

Shocks\Struts\Coils



Recommendation: Front struts look original, recommend replacing them



[Learn More](#)

Tie Rods





Learn More

Wheel Bearings



Learn More

Ball Joints



Drive Line / Axles



Bushings



Sway Bar / Stabilizer Links/Bushings



Recommendation: Found left rear sway bar link loose, needs to be replaced.

Found right rear sway bar link loose, needs to be replaced.



Exhaust



Learn More

Lines/Hoses




Recommendation: Found brake hose have rust , rot , or are damaged and need to be replaced. needs:



Tires

RT Rear Tire



RT Front Tire



LT Rear Tire



LT Front Tire



Brake System

Other



Recommendation: Slave cylinder leaking, needs clutch
Lower control arms looking rotted



Report created on 09/23/2017



Powered By Bolt On Technology™