

Infrastructure Inspection Report

Inspection ID: 1cb2058e-b254-48b5-9b2f-6d94f2ff3023

Asset Health Summary

Health Score	75
Status	MODERATE

Asset Information

Asset Name	OHE-RAIL-59
Asset Type	ohe_rail
Zone	Goa
Installed Year	2012
Latitude	32.0042
Longitude	-0.0029

Inspection Details

Pilot ID	P87
Capture Date	2026-06-16
Validation Status	passed
Analysis Status	completed

Detected Defects

Defect #	1
Type	CORROSION
Severity	CRITICAL
Location	Zone A
Confidence	0.92
AI Reasoning	The AI model detected significant corrosion in Zone A with a confidence score of 0.92, indicating a critical severity level that requires immediate attention to prevent further damage.
AI Recommendation	It is recommended to schedule an urgent maintenance check for Zone A, including a detailed inspection by a qualified technician. Additionally, consider applying anti-corrosion treatments and monitoring the area closely for any signs of progression.

Generated automatically by GridWise AI Inspection Engine