

Infrastructure Inspection Report

Inspection ID: ed1e014f-654a-44b6-a8d7-60245d13b669

Asset Health Summary

Health Score	75
Status	MODERATE

Asset Information

Asset Name	TOWER-A-01
Asset Type	transmission_tower
Zone	Noida
Installed Year	2026
Latitude	0.0015
Longitude	-0.0018

Inspection Details

Pilot ID	P421
Capture Date	2026-06-16
Validation Status	passed
Analysis Status	completed

Detected Defects

Defect #	1
Type	OTHER
Severity	CRITICAL
Location	Hanging wire on the right side of the pole with visible electrical discharge.
Confidence	0.98
AI Reasoning	A conductor is visibly broken and hanging from the pole, with a clear symbol indicating electrical discharge or arcing at its end.
AI Recommendation	Immediately de-energize the affected circuit. Repair or replace the damaged conductor and inspect all connections.

