

Infrastructure Inspection Report

Inspection ID: 846cb779-8318-4d18-9d5a-0e1688dbcc3b

Asset Health Summary

Health Score	75
Status	MODERATE

Asset Information

Asset Name	TOWER-A-01
Asset Type	transmission_tower
Zone	Noida
Installed Year	2026
Latitude	0.0015
Longitude	-0.0018

Inspection Details

Pilot ID	p13
Capture Date	2026-06-16
Validation Status	passed
Analysis Status	completed

Detected Defects

Defect #	1
Type	CRACK
Severity	CRITICAL
Location	Right rail in foreground, complete transverse break
Confidence	1.00
AI Reasoning	The right rail exhibits a complete transverse fracture, resulting in a full separation of the rail and loss of structural continuity.
AI Recommendation	Immediately secure the area. Replace the broken rail section to restore track integrity and ensure operational safety.

