

Infrastructure Inspection Report

Inspection ID: b0a75780-fbd2-4023-858d-dd1054d1dba4

Asset Health Summary

Health Score	85
Status	GOOD

Asset Information

Asset Name	Distribution_pole_12
Asset Type	distribution_pole
Zone	South Distribution
Installed Year	2015
Latitude	0.003
Longitude	-0.0019

Inspection Details

Pilot ID	O0111
Capture Date	2026-06-17 04:57:13.127460+00:00
Validation Status	passed
Analysis Status	completed

Detected Defects

Defect #	1
Type	CORROSION
Severity	MAJOR
Location	Rails and fastening plates along the track section
Confidence	0.92
AI Reasoning	Widespread reddish-brown surface rust and discoloration are visible on the steel rails and metal fastening plates throughout the track section.
AI Recommendation	Assess the depth of corrosion, clean affected areas, and apply protective coatings or consider component replacement.

