

Infrastructure Inspection Report

Inspection ID: 72cabcc5-7153-4c7a-bae4-35ce438b20dc

Asset Health Summary

Health Score	75
Status	MODERATE

Asset Information

Asset Name	TOWER-A-1
Asset Type	transmission_tower
Zone	South Corridor
Installed Year	2015
Latitude	0.0017
Longitude	0.0011

Inspection Details

Pilot ID	P421
Capture Date	2026-06-17 02:37:37.545235+00:00
Validation Status	passed
Analysis Status	completed

Detected Defects

Defect #	1
Type	CORROSION
Severity	CRITICAL
Location	Zone A
Confidence	0.92
AI Reasoning	The AI model detected significant corrosion in Zone A with a confidence score of 0.92, indicating a critical severity level that requires immediate attention to prevent further damage.
AI Recommendation	It is recommended to schedule an urgent maintenance check for Zone A, including a detailed inspection by a qualified technician. Additionally, consider applying anti-corrosion treatments and monitoring the area closely for any signs of progression.

Generated automatically by GridWise AI Inspection Engine