

TRANSPORT AND WAREHOUSE DEPARTMENT

Inter-Office Memo #T&W-26-311



Date : JULY 8, 2026
For : Emily R. Gepilano – SVP Operations
CC : MMD/ACCOUNTING/ADMIN/AUDIT
From : TRANSPORT & WAREHOUSE
SUBJECT : MACHINE AND ACCESSORIES FOR JUNK

Dear Sir/Madam;

We would like to seek for your approval to proceed junking of machines and accessories indicated in the attached list. Per checking, the following machines and accessories are beyond repair and have no book value.

Prepared By:

Raymond Briones
Supervisor – T&W

Checked by :

Arnold Dato
Assistant Manager – T&W

Kimberly Saldo
Manager – Facilities and Admin

William Celi Jr.
Manager-Refurbishing

TRANSPORT AND WAREHOUSE DEPARTMENT

Inter-Office Memo #T&W-26-311



Reviewed by:

Gilbert Masagca
Inventory Analyst – Accounting

Ma. Monette De Vera
Financial Controller

Regine Loyola
Manager - MMD

Verified by :

Ellen Giray
Manager - Audit

Noted by :

Lory Ann Dela Cruz
AVP- Sales Administration

Miguel Canio
SAVP- Customer Service/Rental Sales

Approved by :

Emily R. Gepilano
SVP – Operations

TRANSPORT AND WAREHOUSE DEPARTMENT

Inter-Office Memo #T&W-26-311



SUMMARY:

MODEL	CATEGORY	QTY
BH-223	KM MACHINE	2
BH-283	KM MACHINE	5
BH-287	KM MACHINE	1
BH-363	KM MACHINE	26
BH-364E	KM MACHINE	2
BH-367	KM MACHINE	4
BH-423	KM MACHINE	10
BH-C1060	KM MACHINE	1
BH-C308	KM MACHINE	1
BH-C454	KM MACHINE	1
TOTAL		53

MODEL	CATEGORY	QTY
DF-621	ACCESSORIES	43
DF-624	ACCESSORIES	1
DF-628	ACCESSORIES	5
DF-629	ACCESSORIES	1
DF-701	ACCESSORIES	2
DK-508	ACCESSORIES	6
FS-529	ACCESSORIES	1
FS-533	ACCESSORIES	1
JS-506	ACCESSORIES	1
MB-509	ACCESSORIES	1
PC-208	ACCESSORIES	4
PC-210	ACCESSORIES	3
PC-213	ACCESSORIES	1
PC-409	ACCESSORIES	3
TOTAL		73

MACHINE & ACCESSORIES FOR STRIP 2026	CATEGORY	QTY
	KM MACHINE	53
	RISO MACHINE	0
	NON UBIX MACHI	0
	ACCESSORIES	73
TOTAL		126

LINE #	MACHINE #	MODEL	SERIAL #	CATEGORY	LOCATION	BOOK VALUE (ACCOUNTING REMARKS)	MEMO#
1	1	BH-363	A1UE041112186	KM MACHINE	MF2FBLK01	0	T&W-26-311
2	1	DF-621	A143WY1285384	ACCESSORIES	MF2FBLK01	0	T&W-26-311
3	1	PC-208	A1V4WY2313581	ACCESSORIES	MF2FBLK01	0	T&W-26-311
4	2	BH-223	A1UG011107886	KM MACHINE	MF2FBLK01	0	T&W-26-311
5	2	DF-621	A1V4WY1411953	ACCESSORIES	MF2FBLK01	0	T&W-26-311
6	3	BH-363	A1UE041013655	KM MACHINE	MF2FBLK01	0	T&W-26-311
7	3	DF-621	A143WY1327903	ACCESSORIES	MF2FBLK01	0	T&W-26-311
8	4	BH-223	A1UG011107885	KM MACHINE	MF2FBLK01	0	T&W-26-311
9	4	DF-621	A143WY1411958	ACCESSORIES	MF2FBLK01	0	T&W-26-311
10	4	FS-529	A0U7WY2082335	ACCESSORIES	MF2FBLK01	0	T&W-26-311
11	5	BH-363	A1UE041001689	KM MACHINE	MF2FBLK01	0	T&W-26-311
12	5	DF-621	A143WY1053584	ACCESSORIES	MF2FBLK01	0	T&W-26-311
13	5	PC-208	A1V4WY2312658	ACCESSORIES	MF2FBLK01	0	T&W-26-311
14	6	BH-363	A1UE041118620	KM MACHINE	MF2FBLK01	0	T&W-26-311
15	6	DF-621	A143WY1528455	ACCESSORIES	MF2FBLK01	0	T&W-26-311
16	7	BH-363	A1UE041001804	KM MACHINE	MF2FBLK01	0	T&W-26-311
17	7	DF-621	A143WY1053345	ACCESSORIES	MF2FBLK01	0	T&W-26-311
18	7	PC-208	A1V4WY2006285	ACCESSORIES	MF2FBLK01	0	T&W-26-311
19	8	BH-363	A1UE041009034	KM MACHINE	MF2FBLK01	0	T&W-26-311
20	8	DF-621	A143WY1232458	ACCESSORIES	MF2FBLK01	0	T&W-26-311
21	9	BH-287	A7AH041000347	KM MACHINE	MF2FBLK01	0	T&W-26-311
22	9	DF-628	A7V7WY2058631	ACCESSORIES	MF2FBLK01	0	T&W-26-311
23	10	BH-C454	A4FJ041001559	KM MACHINE	MF2FBLK01	0	T&W-26-311
24	10	DF-701	A3CEWY1046590	ACCESSORIES	MF2FBLK01	0	T&W-26-311
25	10	PC-210	A2XMWY2015535	ACCESSORIES	MF2FBLK01	0	T&W-26-311
26	11	BH-364E	A61F011018300	KM MACHINE	MF2FBLK01	0	T&W-26-311
27	11	DF-701	A3CEWY1313645	ACCESSORIES	MF2FBLK01	0	T&W-26-311
28	11	JS-506	A2YUWY2001296	ACCESSORIES	MF2FBLK01	0	T&W-26-311
29	12	BH-363	A1UE041107176	KM MACHINE	MF2FBLK01	0	T&W-26-311
30	12	DF-621	A143WY1463004	ACCESSORIES	MF2FBLK01	0	T&W-26-311
31	13	BH-283	A1UF041011633	KM MACHINE	MF2FBLK01	0	T&W-26-311
32	13	DF-621	A143WY1233227	ACCESSORIES	MF2FBLK01	0	T&W-26-311
33	14	BH-423	A1UD041001428	KM MACHINE	MF2FBLK01	0	T&W-26-311
34	14	DF-621	A143WY1078230	ACCESSORIES	MF2FBLK01	0	T&W-26-311
35	14	DK-508	A1V4WY4018256	ACCESSORIES	MF2FBLK01	0	T&W-26-311
36	15	BH-363	A1UE041004234	KM MACHINE	MF2FBLK01	0	T&W-26-311

LINE #	MACHINE #	MODEL	SERIAL #	CATEGORY	LOCATION	BOOK VALUE (ACCOUNTING REMARKS)	MEMO#
37	15	DF-621	A143WY1103041	ACCESSORIES	MF2FBLK01	0	T&W-26-311
38	16	BH-364E	A61F041001666	KM MACHINE	MF2FBLK01	0	T&W-26-311
39	16	DF-624	A3CFWY1612276	ACCESSORIES	MF2FBLK01	0	T&W-26-311
40	16	PC-210	A2XMWY8019756	ACCESSORIES	MF2FBLK01	0	T&W-26-311
41	17	BH-423	A1UD011102560	KM MACHINE	MF2FBLK01	0	T&W-26-311
42	17	DF-621	A143WY1280338	ACCESSORIES	MF2FBLK01	0	T&W-26-311
43	18	BH-423	A1UD011111817	KM MACHINE	MF2FBLK01	0	T&W-26-311
44	18	DF-621	A143WY143216	ACCESSORIES	MF2FBLK01	0	T&W-26-311
45	18	PC-409	A1V4WY13104870	ACCESSORIES	MF2FBLK01	0	T&W-26-311
46	19	BH-363	A1UE011002659	KM MACHINE	MF2FBLK01	0	T&W-26-311
47	19	DF-621	A143WY1024360	ACCESSORIES	MF2FBLK01	0	T&W-26-311
48	19	DK-508	A1V4WY4006663	ACCESSORIES	MF2FBLK01	0	T&W-26-311
49	20	BH-423	A1UD041106024	KM MACHINE	MF2FBLK01	0	T&W-26-311
50	20	DF-621	A143WY1461764	ACCESSORIES	MF2FBLK01	0	T&W-26-311
51	21	BH-283	A1UF041114471	KM MACHINE	MF2FBLK01	0	T&W-26-311
52	21	DF-621	A143WY1523269	ACCESSORIES	MF2FBLK01	0	T&W-26-311
53	22	BH-423	A1UD011003522	KM MACHINE	MF2FBLK01	0	T&W-26-311
54	22	DF-621	A143WY1055475	ACCESSORIES	MF2FBLK01	0	T&W-26-311
55	22	PC-409	A1V4WY13005069	ACCESSORIES	MF2FBLK01	0	T&W-26-311
56	23	BH-363	A1UE041111805	KM MACHINE	MF2FBLK01	0	T&W-26-311
57	23	DF-621	A143WY1476493	ACCESSORIES	MF2FBLK01	0	T&W-26-311
58	24	BH-283	A1UF041011545	KM MACHINE	MF2FBLK01	0	T&W-26-311
59	24	DF-621	A143WY1233300	ACCESSORIES	MF2FBLK01	0	T&W-26-311
60	25	BH-363	A1UE041003941	KM MACHINE	MF2FBLK01	0	T&W-26-311
61	25	DF-621	A143WY1104094	ACCESSORIES	MF2FBLK01	0	T&W-26-311
62	25	DK-508	A1V4WY4018250	ACCESSORIES	MF2FBLK01	0	T&W-26-311
63	26	BH-363	A1UE041101639	KM MACHINE	MF2FBLK01	0	T&W-26-311
64	26	DF-621	A143WY1100586	ACCESSORIES	MF2FBLK01	0	T&W-26-311
65	26	PC-409	A1V4WY13107535	ACCESSORIES	MF2FBLK01	0	T&W-26-311
66	27	BH-363	A1UE041008364	KM MACHINE	MF2FBLK01	0	T&W-26-311
67	27	DF-621	A143WY1175135	ACCESSORIES	MF2FBLK01	0	T&W-26-311
68	28	BH-363	A1UE041107486	KM MACHINE	MF2FBLK01	0	T&W-26-311
69	28	DF-621	A143WY1446616	ACCESSORIES	MF2FBLK01	0	T&W-26-311
70	29	BH-423	A1UD041106027	KM MACHINE	MF2FBLK01	0	T&W-26-311
71	29	DF-621	A143WY1461753	ACCESSORIES	MF2FBLK01	0	T&W-26-311
72	30	BH-283	A1UF041014653	KM MACHINE	MF2FBLK01	0	T&W-26-311
73	30	DF-621	A143WY1286085	ACCESSORIES	MF2FBLK01	0	T&W-26-311
74	31	BH-363	A1UE041118667	KM MACHINE	MF2FBLK01	0	T&W-26-311
75	31	DF-621	A143WY1521241	ACCESSORIES	MF2FBLK01	0	T&W-26-311
76	32	BH-363	A1UE041004246	KM MACHINE	MF2FBLK01	0	T&W-26-311
77	32	DF-621	A143WY1104124	ACCESSORIES	MF2FBLK01	0	T&W-26-311
78	32	DK-508	A1V4WY4018241	ACCESSORIES	MF2FBLK01	0	T&W-26-311
79	33	BH-423	A1UD011108388	KM MACHINE	MF2FBLK01	0	T&W-26-311
80	33	DF-621	A143WY1343202	ACCESSORIES	MF2FBLK01	0	T&W-26-311
81	33	DK-508	A1V4WY4017722	ACCESSORIES	MF2FBLK01	0	T&W-26-311
82	34	BH-363	A1UE041012459	KM MACHINE	MF2FBLK01	0	T&W-26-311

LINE #	MACHINE #	MODEL	SERIAL #	CATEGORY	LOCATION	BOOK VALUE (ACCOUNTING REMARKS)	MEMO#
83	34	DF-621	A143WY1286488	ACCESSORIES	MF2FBLK01	0	T&W-26-311
84	35	BH-423	A1UD041001472	KM MACHINE	MF2FBLK01	0	T&W-26-311
85	35	DF-621	A143WY1078124	ACCESSORIES	MF2FBLK01	0	T&W-26-311
86	35	DK-508	A1V4WY4018245	ACCESSORIES	MF2FBLK01	0	T&W-26-311
87	36	BH-363	A1UE041113497	KM MACHINE	MF2FBLK01	0	T&W-26-311
88	36	DF-621	A143WY1483957	ACCESSORIES	MF2FBLK01	0	T&W-26-311
89	37	BH-363	A1UE041118584	KM MACHINE	MF2FBLK01	0	T&W-26-311
90	37	DF-621	A143WY1528458	ACCESSORIES	MF2FBLK01	0	T&W-26-311
91	38	BH-423	A1UD041104292	KM MACHINE	MF2FBLK01	0	T&W-26-311
92	38	DF-621	A143WY1481151	ACCESSORIES	MF2FBLK01	0	T&W-26-311
93	38	PC-208	A1V4WY2311257	ACCESSORIES	MF2FBLK01	0	T&W-26-311
94	39	BH-363	A1UE041008991	KM MACHINE	MF2FBLK01	0	T&W-26-311
95	39	DF-621	A143WY1212392	ACCESSORIES	MF2FBLK01	0	T&W-26-311
96	40	BH-363	A1UE041000835	KM MACHINE	MF2FBLK01	0	T&W-26-311
97	40	DF-621	A143WY1031281	ACCESSORIES	MF2FBLK01	0	T&W-26-311
98	41	BH-363	A1UE041104376	KM MACHINE	MF2FBLK01	0	T&W-26-311
99	41	DF-621	A143WY1417394	ACCESSORIES	MF2FBLK01	0	T&W-26-311
100	42	BH-423	A1UD041100835	KM MACHINE	MF2FBLK01	0	T&W-26-311
101	42	DF-621	A143WY1273226	ACCESSORIES	MF2FBLK01	0	T&W-26-311
102	43	BH-363	A1UE011106962	KM MACHINE	MF2FBLK01	0	T&W-26-311
103	43	DF-621	A143WY1363353	ACCESSORIES	MF2FBLK01	0	T&W-26-311
104	44	BH-283	A1UF041112220	KM MACHINE	MF2FBLK01	0	T&W-26-311
105	44	DF-621	A143WY1502170	ACCESSORIES	MF2FBLK01	0	T&W-26-311
106	45	BH-363	A1UE041118549	KM MACHINE	MF2FBLK01	0	T&W-26-311
107	45	DF-621	A143WY1521288	ACCESSORIES	MF2FBLK01	0	T&W-26-311
108	46	BH-C308	A7PY047003202	KM MACHINE	MC02BLKA14	0	T&W-26-311
109	46	DF-629	A87RWY1379483	ACCESSORIES	MC02BLKA14	0	T&W-26-311
110	47	PC-210	A2XMWY8042876	ACCESSORIES	MC02BLKA14	0	T&W-26-311
111	48	PC-213	A7VAWY2002247	ACCESSORIES	MC02BLKA14	0	T&W-26-311
112	49	FS-533	A2YUWY2007437	ACCESSORIES	MC02BLKA14	0	T&W-26-311
113	50	BH-363	A1UE041005787	KM MACHINE	MC02BLKA14	0	T&W-26-311
114	50	DF-621	A143WY1086278	ACCESSORIES	MC02BLKA14	0	T&W-26-311
115	51	BH-363	A1UE041011669	KM MACHINE	MC02BLKA14	0	T&W-26-311
116	51	DF-621	A143WY1286302	ACCESSORIES	MC02BLKA14	0	T&W-26-311
117	52	BH-367	A789047009297	KM MACHINE	MC02BLKA14	0	T&W-26-311
118	52	DF-628	A7V7WY2405463	ACCESSORIES	MC02BLKA14	0	T&W-26-311
119	53	BH-367	A789047010312	KM MACHINE	MC02BLKA14	0	T&W-26-311
120	53	DF-628	A7V7WY2402534	ACCESSORIES	MC02BLKA14	0	T&W-26-311
121	54	BH-367	A789047004637	KM MACHINE	MC02BLKA14	0	T&W-26-311
122	54	DF-628	A7V7WY2484978	ACCESSORIES	MC02BLKA14	0	T&W-26-311
123	55	BH-367	A789047004757	KM MACHINE	MC02BLKA14	0	T&W-26-311
124	55	DF-628	A7V7WY2319822	ACCESSORIES	MC02BLKA14	0	T&W-26-311
125	56	BH-C1060	A50V041000024	KM MACHINE	MC02BLKA14	0	T&W-26-311
126	56	MB-509	A57WWY1000373	ACCESSORIES	MC02BLKA14	0	T&W-26-311



Machine Evaluation Sheet

Model : 287 ☐ 110V ☐ 220V P/O Date : _____
 Serial No : A7AH041000347 Meter Reading : _____ RR No : _____
 Account / Branch : _____ Location : _____

Findings

☒ No Power ☐ Power OK ☐ Machine Code _____ Tested by : _____

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: _____
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-in	☐ Transformer	Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY	VISUAL
☐ Good Copy _____	☐ Clean ☐ Dirty ☐ Very Dirty
☐ Light Copy _____	☐ Defective Panel <i>Pls. specify</i> _____
☐ Lines on Copy _____	☐ Defective Cassette <i>Pls. specify</i> _____
☐ Dark Copy _____	☐ Defective Parts <i>Pls. specify</i> _____

MECHANICAL	ELECTRICAL
☐ Unusual Noise <i>Pls. specify</i> _____	☐ No Power
☐ Deform Plates <i>Pls. specify</i> _____	☐ F-Codes <i>Pls. specify</i> _____
☐ Detached Ball Caster	☐ Jamming <i>Pls. specify</i> _____
	☐ Stuck-up button <i>Pls. specify</i> _____

Feeding

ADF ☐ OK ☐ Not OK
 Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:		DISPOSITION	REMARKS
DEFECTIVE POWER SUPPLY BROKEN ADV BASE, BRAS BROKEN FOR STRIP		☒ For Strip ☐ Return to WH ☐ For Refurbish	
Assessed <u>Ramh</u>	<u>6.25.24</u>	<u>[Signature]</u> Refurbishing Manager	<u>6/25/24</u> Date
Name	Date		



Machine Evaluation Sheet

Model : C454 ☐ 110V ☐ 220V P/O Date : _____
Serial No : A4FJ04100559 Meter Reading : _____ RR No : _____
Account / Branch : _____ Location : _____

Findings

☐ No Power ☐ Power OK ☐ Machine Code _____ Tested by : _____

MACHINE COMPLETENESS

TERMS

- ☐ Rental
☐ Customer's Unit
☐ Tempo Rental
☐ Demo Unit
☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
☐ Rotary Tray
☐ Working Table
☐ Pedestal
☐ Transformer

OPTIONS

ADU SN: _____
ADF SN: _____
DBU SN: _____
FS SN: _____
Drum No. : _____

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy _____
☐ Light Copy _____
☐ Lines on Copy _____
☐ Dark Copy _____

VISUAL

- ☐ Clean ☐ Dirty ☐ Very Dirty
☐ Defective Panel Pls. specify _____
☐ Defective Cassette Pls. specify _____
☐ Defective Parts Pls. specify _____

MECHANICAL

- ☐ Unusual Noise Pls. specify _____
☐ Deform Plates Pls. specify _____
☐ Detached Ball Caster

ELECTRICAL

- ☐ No Power
☐ F-Codes Pls. specify _____
☐ Jamming Pls. specify _____
☐ Stuck-up button Pls. specify _____

Feeding

- ADF ☐ OK ☐ Not OK
Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

DEFECTIVE MPY BOARD
BROKEN BYPASS, FRONT)
SIDE PANEL FOR STRIP

Assessed by

Name

Date

DISPOSITION

- ☒ For Strip
☐ Return to WH
☐ For Refurbish

REMARKS

Refurbishing Manager

Date

Form # UBX-REF-02

August 2021

Revision No. 03



Machine Evaluation Sheet

Model 364 Autofill 018300 ☐ 110V ☐ 220V P/O Date _____
 Serial No _____ Meter Reading : _____ RR No _____
 Account / Branch : _____ Location : _____

Findings

☐ No Power ☐ Power OK ☐ Machine Code H849 Tested by _____

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: _____
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-in	☐ Transformer	Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY	VISUAL
☐ Good Copy _____	☐ Clean ☐ Dirty ☐ Very Dirty
☐ Light Copy _____	☐ Defective Panel <i>Pls. specify</i> _____
☐ Lines on Copy _____	☐ Defective Cassette <i>Pls. specify</i> _____
☐ Dark Copy _____	☐ Defective Parts <i>Pls. specify</i> _____

MECHANICAL	ELECTRICAL
☐ Unusual Noise <i>Pls. specify</i> _____	☐ No Power
☐ Deform Plates <i>Pls. specify</i> _____	☐ F-Codes <i>Pls. specify</i> _____
☐ Detached Ball Caster	☐ Jamming <i>Pls. specify</i> _____
	☐ Stuck-up button <i>Pls. specify</i> _____

Feeding

ADF ☐ OK ☐ Not OK
 Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:	DISPOSITION	REMARKS
DEFECTIVE MFP, BROKEN SIDE BOARD, BYPASS TRAY FOR STRIP	☒ For Strip ☐ Return to WH ☐ For Refurbish	
Assessed by <u>Plmm</u> <u>6-25-26</u>		<u>6/25/26</u>
Name	Refurbishing Manager	Date



Machine Evaluation Sheet

Model : 283 ☐ 110V ☐ 220V P/O Date : _____
 Serial No : A1U7041011637 Meter Reading : _____ RR No : _____
 Account / Branch : _____ Location : _____

Findings

☐ No Power ☐ Power OK ☐ Machine Code Hong Tested by : _____

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: _____
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-in	☐ Transformer	Drum No. : _____

QUALITY ASSESSMENT

COPY QUALITY	VISUAL
☐ Good Copy _____	☐ Clean ☐ Dirty ☐ Very Dirty
☐ Light Copy _____	☐ Defective Panel <i>Pls. specify</i> _____
☐ Lines on Copy _____	☐ Defective Cassette <i>Pls. specify</i> _____
☐ Dark Copy _____	☐ Defective Parts <i>Pls. specify</i> _____

MECHANICAL	ELECTRICAL
☐ Unusual Noise <i>Pls. specify</i> _____	☐ No Power
☐ Deform Plates <i>Pls. specify</i> _____	☐ F-Codes <i>Pls. specify</i> _____
☐ Detached Ball Caster	☐ Jamming <i>Pls. specify</i> _____
	☐ Stuck-up button <i>Pls. specify</i> _____

Feeding

ADF ☐ OK ☐ Not OK
 Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:	DISPOSITION	REMARKS
DEFECTIVE MTP BOARD BROKEN ADU BASE, BYPASS TRAY FOR STRIP	☒ For Strip ☐ Return to WH ☐ For Refurbish	
Assessed by <u>RAMH</u> <u>6-28-26</u>		<u>6/28/26</u>
Name _____ Date _____	Refurbishing Manager _____	Date _____



Machine Evaluation Sheet

Model : 3642 ☐ 110V ☐ 220V P/O Date : _____
 Serial No : A161704/001664 Meter Reading : _____ RR No : _____
 Account / Branch : _____ Location : _____

Findings

☐ No Power ☐ Power OK ☐ Machine Code _____ Tested by : _____

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: _____
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-In	☐ Transformer	Drum No. : _____

QUALITY ASSESSMENT

COPY QUALITY	VISUAL
☐ Good Copy _____	☐ Clean ☐ Dirty ☐ Very Dirty
☐ Light Copy _____	☐ Defective Panel <i>Pls. specify</i> _____
☐ Lines on Copy _____	☐ Defective Cassette <i>Pls. specify</i> _____
☐ Dark Copy _____	☐ Defective Parts <i>Pls. specify</i> _____

MECHANICAL	ELECTRICAL
☐ Unusual Noise <i>Pls. specify</i> _____	☐ No Power
☐ Deform Plates <i>Pls. specify</i> _____	☐ F-Codes <i>Pls. specify</i> _____
☐ Detached Ball Caster	☐ Jamming <i>Pls. specify</i> _____
	☐ Stuck-up button <i>Pls. specify</i> _____

Feeding

ADF ☐ OK ☐ Not OK
 Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

4

Comments/Recommendation:		DISPOSITION	REMARKS
RAT INTERFER, RUSTY BODY ANGLE, BROKEN ADV BASE FOR STRIP		☒ For Strip ☐ Return to WH ☐ For Refurbish	
Assessed by <u>mmh</u>	Date <u>6-25-20</u>	Refurbishing Manager <u>[Signature]</u>	Date <u>6/25/20</u>
Name	Date	Refurbishing Manager	Date



Machine Evaluation Sheet

Model : 363 AIUF04/000835 ☐ 110V ☐ 220V P/O Date : _____
Serial No : _____ Meter Reading : _____ RR No : _____
Account / Branch : _____ Location : _____

Findings

☐ No Power ☐ Power OK ☐ Machine Code _____ Tested by : _____

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: _____
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-in	☐ Transformer	Drum No. : _____

QUALITY ASSESSMENT

COPY QUALITY

☐ Good Copy _____
☐ Light Copy _____
☐ Lines on Copy _____
☐ Dark Copy _____

VISUAL

☐ Clean ☐ Dirty ☐ Very Dirty
☐ Defective Panel *Pls. specify* _____
☐ Defective Cassette *Pls. specify* _____
☐ Defective Parts *Pls. specify* _____

MECHANICAL

☐ Unusual Noise *Pls. specify* _____
☐ Deform Plates *Pls. specify* _____
☐ Detached Ball Caster

ELECTRICAL

☐ No Power
☐ F-Codes *Pls. specify* _____
☐ Jamming *Pls. specify* _____
☐ Stuck-up button *Pls. specify* _____


Feeding

ADF ☐ OK ☐ Not OK
Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC



Comments/Recommendation:		DISPOSITION	REMARKS
<u>RAT INFESTED, DEFECTIVE</u> <u>WIRINGS, RUSTY BODY</u> <u>ANGE</u> <u>FOR STRIP</u>		☒ For Strip ☐ Return to WH ☐ For Refurbish	
Assessed <u>PMH</u>	<u>6-25-26</u>		<u>6/25/26</u>
Name	Date	Refurbishing Manager	Date

UBX

Machine Evaluation Sheet

Model 203
 Serial No AWFO41112220
 Account / Branch : _____

☐ 110V ☐ 220V

Meter Reading : _____

Location : _____

P/O Date : _____

RR No : _____

Findings

☐ No Power

☐ Power OK

☐ Machine Code _____

Tested by : PMW

MACHINE COMPLETENESS

TERMS

- ☐ Rental
- ☐ Customer's Unit
- ☐ Tempo Rental
- ☐ Demo Unit
- ☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
- ☐ Rotary Tray
- ☐ Working Table
- ☐ Pedestal
- ☐ Transformer

OPTIONS

ADU SN: _____

ADF SN: DF-001

DBU SN: A143WY150

FS SN: _____

Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy
- ☐ Light Copy
- ☐ Lines on Copy
- ☐ Dark Copy

VISUAL

☐ Clean

☒ Dirty

☐ Very Dirty

☐ Defective Panel

Pls. specify

BYPASS TRAY, ADU BASE

☐ Defective Cassette Pls. specify _____

☐ Defective Parts

Pls. specify _____

MECHANICAL

☐ Unusual Noise Pls. specify _____

☐ Deform Plates Pls. specify _____

☐ Detached Ball Caster

Feeding

ADF ☐ OK

☒ Not OK

Cassette ☐ OK

☒ Not OK

ELECTRICAL

☐ No Power

☐ F-Codes

Pls. specify _____

☐ Jamming

Pls. specify _____

☐ Stuck-up button Pls. specify _____

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

PROBLEM ADU BASE, BY PASS
TRAY, CASSETTE BASE,
DEFORMED ADF OPEN/CLOSED
DEFECTIVE OPERATION UNIT
FOR STRIP

Assessed PMW

6-19-20

Name

Date

DISPOSITION

☒ For Strip

☐ Return to WH

☐ For Refurbish

REMARKS

Refurbishing Manager

Date

6/17/20

Form # UBX-REF-02

August 2021

Revision No. 03

UBX**Machine Evaluation Sheet**

Model

Serial No

Account / Branch

Findings☐ No Power☐ Power OK☐ Machine Code☐ 110V☐ 220V

Meter Reading

Location

P/O Date

RR No

Tested by

MACHINE COMPLETENESS**TERMS**☐ Rental☐ Customer's Unit☐ Tempo Rental☐ Demo Unit☐ Trade-in**ACCESSORIES**☐ Delivery Tray☐ Rotary Tray☐ Working Table☐ Pedestal☐ Transformer**OPTIONS**

ADU SN:

ADF SN:

DBU SN:

FS SN:

Drum No.

QUALITY ASSESSMENT**COPY QUALITY**☐ Good Copy☐ Light Copy☐ Lines on Copy☐ Dark Copy**VISUAL**☐ Clean☒ Dirty☐ Very Dirty☐ Defective Panel

Pls. specify

☒ Defective Cassette

Pls. specify

☐ Defective Parts

Pls. specify

MECHANICAL☐ Unusual Noise Pls. specify☐ Deform Plates Pls. specify☐ Detached Ball Caster

Feeding

ADF ☐ OK☒ Not OKCassette ☐ OK☐ Not OK**ELECTRICAL**☐ No Power☐ F-Codes

Pls. specify

☐ Jamming

Pls. specify

☐ Stuck-up button Pls. specify**MACHINE RATING**

Note: Choose from 1-4; 1 being the highest

3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

Comments/Recommendation:

OVERLY HANG DEFECTIVE APP
BOARD, BYPASS LIFT UP &
TRAY BROKEN CASSETTE
COVER BROKEN FOR STRIP

Assessed by:

Name

Date

DISPOSITION☒ For Strip☐ Return to WH☐ For Refurbish**REMARKS**

Refurbishing Manager

Date

Form # UBX-REF-02

August 2021

Revision No. 03



Machine Evaluation Sheet

Model: C208 ☐ 110V ☐ 220V P/O Date: _____
Serial No: A7P4047003202 Meter Reading: _____ RR No: _____
Account / Branch: _____ Location: _____

Findings

☐ No Power

☐ Power OK

☐ Machine Code

Hard / Sudden Shutdown

Tested by: mm

MACHINE COMPLETENESS

TERMS

- ☐ Rental
☐ Customer's Unit
☐ Tempo Rental
☐ Demo Unit
☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
☐ Rotary Tray
☐ Working Table
☐ Pedestal
☐ Transformer

OPTIONS

ADU SN:

ADF SN:

DBU SN:

FS SN:

Drum No.:

DF-09-A87RMY079483

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy
☐ Light Copy
☐ Lines on Copy
☐ Dark Copy

VISUAL

☐ Clean ☐ Dirty ☐ Very Dirty

☐ Defective Panel Pls. specify

BROKE BYPASS TRAY, ADF TRAY

☐ Defective Cassette Pls. specify

☐ Defective Parts Pls. specify

MECHANICAL

☐ Unusual Noise Pls. specify

☐ Deform Plates Pls. specify

☐ Detached Ball Caster

ELECTRICAL

☐ No Power

☐ F-Codes Pls. specify

☐ Jamming Pls. specify

☐ Stuck-up button Pls. specify

Feeding

ADF ☐ OK

☐ Not OK

Cassette ☐ OK

☐ Not OK

MACHINE RATING

Note: Choose from 1-4; 1 being the highest

3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

DEFECTIVE MFP BOARD,
BROKEN BYPASS TRAY,
SIDE PANEL, ADF TRAY
FOR STRIP

Assessed by: mm

Name

Date

7-3-26

DISPOSITION

☒ For Strip

☐ Return to WH

☐ For Refurbish

REMARKS

[Signature]
Refurbishing Manager

7/3/26

Date



Machine Evaluation Sheet

Model : 303 ☐ 110V ☐ 220V P/O Date : 7/1
 Serial No : AIVE041005787 Meter Reading : 7 RR No : 1
 Account / Branch : _____ Location : 7

Findings

☐ No Power ☐ Power OK ☐ Machine Code _____ Tested by : PRMN

MACHINE COMPLETENESS

TERMS

- ☐ Rental
☐ Customer's Unit
☐ Tempo Rental
☐ Demo Unit
☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
☐ Rotary Tray
☐ Working Table
☐ Pedestal
☐ Transformer

OPTIONS

ADU SN: DFU21-A142WY10SC278
 ADF SN: _____
 DBU SN: _____
 FS SN: _____
 Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy
☐ Light Copy
☐ Lines on Copy
☐ Dark Copy

VISUAL

- ☐ Clean ☒ Dirty ☐ Very Dirty
☒ Defective Panel Pls. specify ADU BASE & BY PASS
☒ Defective Cassette Pls. specify CASSETTE BASE BROKEN
☐ Defective Parts Pls. specify _____

MECHANICAL

- ☐ Unusual Noise Pls. specify _____
☐ Deform Plates Pls. specify _____
☐ Detached Ball Caster

ELECTRICAL

- ☐ No Power
☐ F-Codes Pls. specify _____
☐ Jamming Pls. specify _____
☐ Stuck-up button Pls. specify _____

Feeding

- ADF ☐ OK ☒ Not OK
 Cassette ☐ OK ☒ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

SUDDENLY SHUTDOWN
DEFECTIVE MFP BOARD,
BROKEN BYPASS TRAY &
ADU BASE
FOR STRIP
 Asse: PRMN 6-5-20

DISPOSITION

- ☒ For Strip
☐ Return to WH
☐ For Refurbish

REMARKS

[Signature]
 Refurbishing Manager

6/4/20

Date



Machine Evaluation Sheet

Model

Serial No.

Account / Branch

☐ 110V

☐ 220V

Meter Reading

Location

P/O Date

RR No

Findings

☐ No Power

☐ Power OK

☐ Machine Code

Tested by

MACHINE COMPLETENESS

TERMS

- ☐ Rental
☐ Customer's Unit
☐ Tempo Rental
☐ Demo Unit
☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
☐ Rotary Tray
☐ Working Table
☐ Pedestal
☐ Transformer

OPTIONS

ADU SN:

ADF SN:

DBU SN:

FS SN:

Drum No.:

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy
☐ Light Copy
☐ Lines on Copy
☐ Dark Copy

VISUAL

- ☐ Clean ☒ Dirty ☐ Very Dirty
☒ Defective Panel Pls. specify BROKEN ADU BASE AND BYPASS
☐ Defective Cassette Pls. specify
☐ Defective Parts Pls. specify

MECHANICAL

- ☐ Unusual Noise Pls. specify
☐ Deform Plates Pls. specify
☐ Detached Ball Caster

ELECTRICAL

- ☐ No Power
☐ F-Codes Pls. specify
☐ Jamming Pls. specify
☐ Stuck-up button Pls. specify

Feeding

ADF ☐ OK

☒ Not OK

Cassette ☐ OK

☐ Not OK

MACHINE RATING

Note: Choose from 1-4; 1 being the highest
 3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

DEFECTIVE OPERATION UNIT
 HARD TOUCH, BROKEN ADU
 BASE, BYPASS TRAY, AND
 ADF IPIN / CLOSE FOR STRIP

Assessed by

Name

Date

DISPOSITION

- ☒ For Strip
☐ Return to WH
☐ For Refurbish

REMARKS

Refurbishing Manager

Date



Machine Evaluation Sheet

Model : 367 ☐ 110V ☐ 220V P/O Date : 1/1
Serial No : A789047009297 Meter Reading : 1/2 RR No : 1/1
Account / Branch : _____ Location : _____
Findings
☐ No Power ☐ Power OK ☐ Machine Code _____ Tested by : Roman

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: <u>DT-628-A7V7WY 2465463</u>
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-in	☐ Transformer	Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY	VISUAL
☐ Good Copy _____	☐ Clean ☐ Dirty ☒ Very Dirty
☐ Light Copy _____	☒ Defective Panel Pls. specify <u>ADF AND ROTARY BROKEN</u>
☐ Lines on Copy _____	☐ Defective Cassette Pls. specify _____
☐ Dark Copy _____	☐ Defective Parts Pls. specify _____

MECHANICAL	ELECTRICAL
☐ Unusual Noise Pls. specify _____	☐ No Power
☐ Deform Plates Pls. specify _____	☐ F-Codes Pls. specify _____
☐ Detached Ball-Caster	☐ Jamming Pls. specify _____
Feeding	☐ Stuck-up button Pls. specify _____
ADF ☐ OK ☒ Not OK	
Cassette ☐ OK ☐ Not OK	

MACHINE RATING
Note : Choose from 1-4; 1 being the highest
3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

RUSTY BODY ANGLE, HANG
DEFECTIVE MFP BOARD
BROKEN ADU, FOR STRIP
ADF ROTARY

Assessed by Roman

5-15-20

Name

Date

DISPOSITION


☒ For Strip
☐ Return to WH
☐ For Refurbish

REMARKS

[Signature]
Refurbishing Manager

6/4/26

Date



Machine Evaluation Sheet

Model 367 ☐ 110V ☒ 220V P/O Date : 7/1
Serial No A789047010312 Meter Reading : 17 RR No : 1
Account / Branch : _____ Location : 6
Findings
☐ No Power ☒ Power OK ☐ Machine Code C535V Tested by : RPMR

MACHINE COMPLETENESS

TERMS

- ☐ Rental
- ☐ Customer's Unit
- ☐ Tempo Rental
- ☐ Demo Unit
- ☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
- ☐ Rotary Tray
- ☐ Working Table
- ☐ Pedestal
- ☐ Transformer

OPTIONS

ADU SN: VF628-A7V7W72402534
ADF SN: _____
DBU SN: _____
FS SN: _____
Drum No. : _____

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy
- ☐ Light Copy
- ☐ Lines on Copy
- ☐ Dark Copy

VISUAL

- ☐ Clean ☐ Dirty ☐ Very Dirty
- ☐ Defective Panel Pls. specify _____
- ☒ Defective Cassette Pls. specify CASSETT BASE 1 TRAY BROKEN
- ☐ Defective Parts Pls. specify _____

MECHANICAL

- ☐ Unusual Noise Pls. specify _____
- ☐ Deform Plates Pls. specify _____
- ☐ Detached Ball-Caster

ELECTRICAL

- ☐ No Power
- ☐ F-Codes Pls. specify _____
- ☐ Jamming Pls. specify _____
- ☐ Stuck-up button Pls. specify _____

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

DEFECTIVE MFP AND
HIGH VOLTAGE BOARD,
OPERATION UNIT FOR STRIP

Assessed by RPMR

Date 5-15-26

Name

Date

DISPOSITION

- ☒ For Strip
- ☐ Return to WH
- ☐ For Refurbish

REMARKS

[Signature]
Refurbishing Manager

Date 6/4/26

Date



Machine Evaluation Sheet

Model : 367 ☐ 110V ☐ 220V P/O Date : _____
Serial No : A729047004637 Meter Reading : _____ RR No : _____
Account / Branch : _____ Location : _____

Findings

☐ No Power ☐ Power OK ☐ Machine Code _____ Tested by : _____

MACHINE COMPLETENESS

TERMS

- ☐ Rental
☐ Customer's Unit
☐ Tempo Rental
☐ Demo Unit
☐ Trade-in

ACCESSORIES

- ☐ Delivery Tray
☐ Rotary Tray
☐ Working Table
☐ Pedestal
☐ Transformer

OPTIONS

ADU SN: _____
ADF SN: _____
DBU SN: _____
FS SN: _____
Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY

- ☐ Good Copy _____
☐ Light Copy _____
☐ Lines on Copy _____
☐ Dark Copy _____

VISUAL

- ☐ Clean ☐ Dirty ☐ Very Dirty
☐ Defective Panel *Pls. specify* _____
☐ Defective Cassette *Pls. specify* _____
☐ Defective Parts *Pls. specify* _____

MECHANICAL

- ☐ Unusual Noise *Pls. specify* _____
☐ Deform Plates *Pls. specify* _____
☐ Detached Ball Caster

ELECTRICAL

- ☐ No Power
☐ F-Codes *Pls. specify* _____
☐ Jamming *Pls. specify* _____
☐ Stuck-up button *Pls. specify* _____

Feeding

- ADF ☐ OK ☐ Not OK
Cassette ☐ OK ☐ Not OK

MACHINE RATING

Note : Choose from 1-4; 1 being the highest
3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

4

Comments/Recommendation:

PAT INFESTED
DEFECTIVE MFP BOARD
FOR STRIP

Assessed by RAMA

Name

6-25-21

Date

DISPOSITION

- ☒ For Strip
☐ Return to WH
☐ For Refurbish

REMARKS

[Signature]
Refurbishing Manager

6/25/21

Date



Machine Evaluation Sheet

Model: 367 ☐ 110V ☐ 220V P/O Date: 7/1
Serial No: A789047004757 Meter Reading: 7/2 RR No: 7/k
Account / Branch: _____ Location: _____
Findings
☐ No Power ☐ Power OK ☐ Machine Code C135U Tested by: Phon

MACHINE COMPLETENESS

TERMS	ACCESSORIES	OPTIONS
☐ Rental	☐ Delivery Tray	ADU SN: <u>DF-028 A7V7W42319822</u>
☐ Customer's Unit	☐ Rotary Tray	ADF SN: _____
☐ Tempo Rental	☐ Working Table	DBU SN: _____
☐ Demo Unit	☐ Pedestal	FS SN: _____
☐ Trade-in	☐ Transformer	Drum No.: _____

QUALITY ASSESSMENT

COPY QUALITY	VISUAL
☐ Good Copy	☐ Clean ☐ Dirty ☐ Very Dirty
☐ Light Copy	☒ Defective Panel Pls. specify <u>BYPASS BROKEN</u>
☐ Lines on Copy	☒ Defective Cassette Pls. specify <u>CASSETTE COVER</u>
☐ Dark Copy	☐ Defective Parts Pls. specify _____

MECHANICAL	ELECTRICAL
☐ Unusual Noise Pls. specify _____	☐ No Power
☐ Deform Plates Pls. specify _____	☐ F-Codes Pls. specify <u>7</u>
☐ Detached Ball-Caster	☐ Jamming Pls. specify _____
	☐ Stuck-up button Pls. specify _____

Feeding

ADF ☐ OK ☒ Not OK
Cassette ☐ OK ☒ Not OK

MACHINE RATING

Note: Choose from 1-4; 1 being the highest
3 & 4 is not acceptable

TO BE FILLED UP BY DIAGNOSTIC

3

Comments/Recommendation:

DEFECTIVE MFP BOARD,
FIRMWARE DIENT WORK
WRITE UNIT DEFECTIVE,
HARDWARES FOR STRIP

Assessed by: Ran h 5-15-26
Name Date

DISPOSITION

☒ For Strip
☐ Return to WH
☐ For Refurbish

REMARKS

[Signature]
Refurbishing Manager

6/4/26
Date

#	MACHINE #	MODEL	SERIAL #	CATEGORY	LOCATION	BOOK VALUE (ACCOUNTING REMARKS)	MEMO#	REMARKS
1	1	BH-363	A1UE041112186	KM MACHINE	MF2FBLK01	0	T&W-26-311	DEFECTIVE OPERATION & BROKEN CASSETTES
4	2	BH-223	A1UG011107886	KM MACHINE	MF2FBLK01	0	T&W-26-311	
6	3	BH-363	A1UE041013655	KM MACHINE	MF2FBLK01	0	T&W-26-311	
8	4	BH-223	A1UG011107885	KM MACHINE	MF2FBLK01	0	T&W-26-311	
11	5	BH-363	A1UE041001689	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
14	6	BH-363	A1UE041118620	KM MACHINE	MF2FBLK01	0	T&W-26-311	
16	7	BH-363	A1UE041001804	KM MACHINE	MF2FBLK01	0	T&W-26-311	
19	8	BH-363	A1UE041009034	KM MACHINE	MF2FBLK01	0	T&W-26-311	
29	12	BH-363	A1UE041107176	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
33	14	BH-423	A1UD041001428	KM MACHINE	MF2FBLK01	0	T&W-26-311	
36	15	BH-363	A1UE041004234	KM MACHINE	MF2FBLK01	0	T&W-26-311	
41	17	BH-423	A1UD011102560	KM MACHINE	MF2FBLK01	0	T&W-26-311	
43	18	BH-423	A1UD01111817	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
46	19	BH-363	A1UE011002659	KM MACHINE	MF2FBLK01	0	T&W-26-311	
49	20	BH-423	A1UD041106024	KM MACHINE	MF2FBLK01	0	T&W-26-311	
51	21	BH-283	A1UF041114471	KM MACHINE	MF2FBLK01	0	T&W-26-311	
53	22	BH-423	A1UD011003522	KM MACHINE	MF2FBLK01	0	T&W-26-311	DEFECTIVE MFP BOARD
56	23	BH-363	A1UE041111805	KM MACHINE	MF2FBLK01	0	T&W-26-311	
58	24	BH-283	A1UF041011545	KM MACHINE	MF2FBLK01	0	T&W-26-311	
60	25	BH-363	A1UE041003941	KM MACHINE	MF2FBLK01	0	T&W-26-311	
63	26	BH-363	A1UE041101639	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
66	27	BH-363	A1UE041008364	KM MACHINE	MF2FBLK01	0	T&W-26-311	
68	28	BH-363	A1UE041107486	KM MACHINE	MF2FBLK01	0	T&W-26-311	
70	29	BH-423	A1UD041106027	KM MACHINE	MF2FBLK01	0	T&W-26-311	
72	30	BH-283	A1UF041014653	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
74	31	BH-363	A1UE041118667	KM MACHINE	MF2FBLK01	0	T&W-26-311	
76	32	BH-363	A1UE041004246	KM MACHINE	MF2FBLK01	0	T&W-26-311	
79	33	BH-423	A1UD011108388	KM MACHINE	MF2FBLK01	0	T&W-26-311	
82	34	BH-363	A1UE041012459	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
84	35	BH-423	A1UD041001472	KM MACHINE	MF2FBLK01	0	T&W-26-311	
87	36	BH-363	A1UE041113497	KM MACHINE	MF2FBLK01	0	T&W-26-311	
89	37	BH-363	A1UE041118584	KM MACHINE	MF2FBLK01	0	T&W-26-311	
91	38	BH-423	A1UD041104292	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
94	39	BH-363	A1UE041008991	KM MACHINE	MF2FBLK01	0	T&W-26-311	
98	41	BH-363	A1UE041104376	KM MACHINE	MF2FBLK01	0	T&W-26-311	
100	42	BH-423	A1UD041100835	KM MACHINE	MF2FBLK01	0	T&W-26-311	
102	43	BH-363	A1UE011106962	KM MACHINE	MF2FBLK01	0	T&W-26-311	EOL
125	56	BH-C1060	A50V041000024	KM MACHINE	MC02BLKA14	0	T&W-26-311	

