



الجمهورية العربية السورية — محافظة حلب

Aleppo Civil Council

المجلس المدني لحلب

Structural Safety and Disaster Assessment Unit

REFERENCE

ACC-2025-0

Issued: 14 March 2025

ORIGINAL — NOT A

STRUCTURAL DAMAGE ASSESSMENT LETTER — CATEGORY 2 / CATEGORY 3

تقرير تقييم الأضرار الهيكلية — الفئة الثانية / الفئة الثالثة

RE: Seismic Aftershock Damage Assessment — Al-Nour Street, Block 4, Kafr Halab, Aleppo Governorate

This letter is issued by the Aleppo Civil Council Structural Safety and Disaster Assessment Unit (SSDA) pursuant to site inspection conducted on **14–15 March 2025** in response to seismic aftershock activity recorded from **18–22 February 2025** (primary tremor magnitude estimated 4.8 ML, Kandilli Observatory cross-reference KO-2025-ALP-0028). The inspections covered four residential units on Al-Nour Street, Block 4, Kafr Halab District, Aleppo Governorate. This assessment is issued at the written request of Ms. **Hassan**, resident of Unit 4-B, for purposes of relief and humanitarian assistance applications.

INSPECTED PROPERTIES — SUMMARY

UNIT ID	ADDRESS	OCCUPANTS	DAMAGE CATEGORY	PRIMARY STRUCTURAL FINDING
4-A	Al-Nour St., Block 4, Ground Floor	8 persons (2 families)	CAT-3 PARTIAL COLLAPSE	Eastern load-bearing wall failure; roof sag > 35°; uninhabitable
4-B	Al-Nour St., Block 4, First Floor	5 persons — Layla Hassan household	CAT-3 PARTIAL COLLAPSE	Eastern wall partial failure; floor joists compromised; structural entry risk
4-C	Al-Nour St., Block 4, Ground Floor (adj.)	12 persons (3 families)	CAT-2 SEVERE DAMAGE	Foundation crack propagation; wind frames sheared; conditional habitability
4-D	Al-Nour St., Block 4, Second Floor	22 persons (5 families)	CAT-2 SEVERE DAMAGE	Stairwell support cracking; balcony parapet failure; restricted access

ASSESSMENT FINDINGS

- Units 4-A and 4-B are classified **Category 3 (Partial Collapse)** under the ACC Rapid Damage Assessment Protocol (RDAP-2019, Rev. 3). Immediate reoccupation is **prohibited**. A structural engineer's remediation plan is required before any repair works may commence.
- Units 4-C and 4-D are classified **Category 2 (Severe Damage)**. Conditional habitation is permitted with reinforcement of identified crack zones within 30 days. Balcony access is closed pending parapet reconstruction.
- The shared rooftop water tank (500L capacity, cast concrete) sustained a hairline fracture resulting in contamination risk. Immediate decommission and replacement recommended. Estimated affected households: all four units above (total 47 persons).
- No fatalities were recorded. Two minor injuries (dust inhalation, paediatric — treated at Al-Salam Clinic, Kafr Halab) were documented. Displacement of the 13 households in 4-A and 4-B is ongoing as of assessment date.

5 Assessment countersigned by Kafr Halab Neighbourhood Relief Committee Chairperson **Mr. Bilal Nasser Al-Kurdi** (KHNRC ref. KH-RC-2019-114) following site walk on 15 March 2025.

DISPLACED HOUSEHOLD SUMMARY (UNITS 4-A AND 4-B)

HOUSEHOLD	HEAD OF HOUSEHOLD	NO. OF PERSONS	CURRENT SHELTER
Unit 4-A, HH-1	Ibrahim Qasem Al-Sayed	4 (incl. 2 children)	Hosted by relative — Bab Al-Faraj
Unit 4-A, HH-2	Umm Khalil Barakat	4 (incl. 3 children)	Hosted in 4-C common hallway (temporary)
Unit 4-B, HH-1	Layla Hassan (applicant)	5 (incl. 3 children, 1 infant)	Hosted in adjacent building — Abu Walid Qasem property

PRELIMINARY HUMANITARIAN NEEDS ESTIMATE

ITEM	SCOPE	EST. COST (USD)	PRIORITY
Emergency structural repair materials (cement, rebar, corrugated sheeting)	4 units (Cat-2 + Cat-3)	4,200	IMMEDIATE
Water tank replacement (500L, food-grade polypropylene)	Block 4 shared supply	650	IMMEDIATE
Food-security buffer (2 months, 47 displaced persons)	All 4 units	1,800	URGENT
Total Estimated Need		USD 6,650	

OFFICIAL CERTIFICATION

The Aleppo Civil Council Structural Safety and Disaster Assessment Unit certifies that the damage described in this letter was independently verified by two qualified structural surveyors and countersigned by a community liaison. This letter constitutes an official assessment document for the purposes of humanitarian assistance applications, insurance claims, and relief fund disbursements. Reference **ACC-2025-0847** is a unique document identifier; any purported copy should be verified against the SSDA registry.

Eng. Marwan Al-Atassi
Lead Structural Surveyor
SSDA — Aleppo Civil Council

Dr. Suha Qabbani
Director, Assessment Unit
Aleppo Civil Council

Bilal Nasser Al-Kurdi
Chairperson
Kafr Halab Neighbourhood Relief Committee