



**HQ OFFICE**  
4th Floor, CPA Center,  
Thika Road, Survey,  
Nairobi, Kenya

Telephone +254 716 400 403  
+254 795 400 403  
Email info@gimbo.co.ke  
Website www.gimbo.co.ke

**NO.50**

## **CERTIFICATE OF DE-INSTALLATION**

### VEHICLE TRACKING SYSTEM

We hereby declare vehicle tracking system device has been de-installed

**Customer Name**

JOHNESS NGUTA MBAKA

**Destination**

NIRVANA CREDIT

**Engine number**

HR12-068271A

**Vehicle Reg no**

KDD 106B

**Security office model**

COMBO

**Ei number**

**Chassis number**

E12-418583

**Date**

2025-12-19

**Color**

BLACK

**Signatory Name**

PAUL KARANJA



Failure due to accidents or damages to either vehicle or the units is not covered by the warranty. The warranty is limited to the replacement of faulty parts and components and the repair of the unit. The warranty becomes null and void if the unit has been tampered with, repaired or damaged by unauthorized person.