

ASSET MAINTENANCE & ENGINEERING ACTION REPORT

MATRIX GROUP GLOBAL LLC • CORPORATE FACILITIES & EQUIPMENT INFRASTRUCTURE REGISTRY

Work Order ID	MNT-2026-303	Execution Date	May 30, 2026
Target Asset Name	Emergency Backup Diesel Generator		
Assigned Technician	Carlos Mendez, Logistics Supervisor	Physical Location	Warehouse South, Exterior Platform

CURRENT MAINTENANCE STATUS: COMPLETED

1. REPORTED ISSUE / DIAGNOSTIC BASELINE FAULTS

Routine monthly load testing revealed an intermittent voltage drop across the secondary automatic transfer switch.

2. CORRECTIVE REMEDIATION ACTIONS EXECUTED

Cleaned oxidation from high-voltage contact terminals, replaced the primary fuel filters, and completed a successful 60-minute full-load test.

This document serves as an authorized technical record. All post-maintenance asset metrics have been verified against corporate equipment safety rules and re-logged into the primary operational framework dashboard.

Field Technician Signature

Facilities Operations Sign-off