

ASSET MAINTENANCE & ENGINEERING ACTION REPORT

MATRIX GROUP GLOBAL LLC • CORPORATE FACILITIES & EQUIPMENT INFRASTRUCTURE REGISTRY

Work Order ID	MNT-2026-314	Execution Date	May 30, 2026
Target Asset Name	Corporate Executive Vehicle - Car #3		
Assigned Technician	Elena Rostova, VP of Operations	Physical Location	HQ Ground Parking Garage

CURRENT MAINTENANCE STATUS: COMPLETED

1. REPORTED ISSUE / DIAGNOSTIC BASELINE FAULTS

Automated fleet monitoring logs flagged a brake pad wear sensor warning indicator during routine weekly vehicle data synchronization.

2. CORRECTIVE REMEDIATION ACTIONS EXECUTED

Replaced worn front brake pads, swapped out the triggered electrical wear sensors, and verified vehicle system status metrics.

This document serves as an authorized technical record. All post-maintenance asset metrics have been verified against corporate equipment safety rules and re-logged into the primary operational framework dashboard.

Field Technician Signature

Facilities Operations Sign-off