

ASSET MAINTENANCE & ENGINEERING ACTION REPORT

MATRIX GROUP GLOBAL LLC • CORPORATE FACILITIES & EQUIPMENT INFRASTRUCTURE REGISTRY

Work Order ID	MNT-2026-315	Execution Date	May 30, 2026
Target Asset Name	Uninterrupted Power Supply (UPS) Bank C		
Assigned Technician	Liam Brookes, IT Support	Physical Location	Main Datacenter Power Room

CURRENT MAINTENANCE STATUS: COMPLETED

1. REPORTED ISSUE / DIAGNOSTIC BASELINE FAULTS

Diagnostic dashboard checks highlighted battery cell resistance variations inside block number 4, posing runtime risks.

2. CORRECTIVE REMEDIATION ACTIONS EXECUTED

Isolated the target string from the live circuit safely, hot-swapped three failing lead-acid battery cells, and completed a load balance calibration.

This document serves as an authorized technical record. All post-maintenance asset metrics have been verified against corporate equipment safety rules and re-logged into the primary operational framework dashboard.

Field Technician Signature

Facilities Operations Sign-off