

VinyasGen Proposal Report

Layout: Maximum Parking

Site area: 2401.87 sqm

Green Cover: 7.4%

Built Coverage: 0.0%

Organized parking: 53 spaces

Trees: 6

Livability Score: 39/100

Emergency Access: FAIL

Compliance Summary

Overall status: violation

Green Area: Green Area: actual 7.4%; required minimum 15.0%. Citation: Noida Building Bye-Laws (as amended) - PLACEHOLDER, verify with official source; min_green_area_pct; value=0.15

Ground Coverage: Ground Coverage: actual 0.0%; required maximum 35.0%. Citation: Noida Building Bye-Laws (as amended) - PLACEHOLDER, verify with official source; max_ground_coverage_pct; value=0.35

FAR: FAR: actual 0.000; required maximum 3.500. Citation: Noida Building Bye-Laws (as amended) - PLACEHOLDER, verify with official source; max_far; value=3.5

Two-Wheeler Parking: Two-Wheeler Parking: actual 53.00 bays; required minimum 24.00 bays. Citation: Noida Building Bye-Laws (as amended) - PLACEHOLDER, verify with official source; parking_norms.two_wheeler_per_100sqm; value=1.0

Emergency Clear Width: Emergency Clear Width: actual 13.68m; required minimum 4.50m. Citation: Noida Building Bye-Laws (as amended) - PLACEHOLDER, verify with official source; fire_safety.min_clear_access_width_m; value=4.5

Regulation Review: Regulation values are pending human verification. Citation: Noida Building Bye-Laws (as amended) - PLACEHOLDER, verify with official source; review_status; value=pending_review

Disclaimer

VinyasGen is a decision-support and visualization tool. All outputs - layouts, compliance results, cost estimates, and encroachment flags - are indicative only, based on digitized regulatory data, and do not constitute statutory approval, legal measurement, or enforcement action. All proposals must be verified with the relevant municipal authority before implementation. Encroachment flags are potential indicators requiring field verification - they do not constitute legal evidence.