

Inspection Report

Generated 08 July 2026, 11:21 IST

Inspection Summary

Inspection Name	Zone D — Excavation Site (11:01 AM)
Workers Detected	13
Total Violations	3
Compliance Score	85.0%
Status	FLAGGED
Recorded	08 Jul 2026, 16:31 IST

Violation Breakdown

Category	Count
Helmet	1
Vest	0
Scaffolding	0
Debris	0
Restricted Zone	1
Fall Protection	0
Heavy Equipment	0
Unsafe Behaviour	0
Material Storage	1

Individual Violations

Violation	Category	Severity	Count	Time (IST)
Helmet is mandatory in all active work zones	Helmet	High	1	08 Jul, 16:31

No unauthorised entry into restricted zones	Restricted Zone	Critical	1	08 Jul, 16:31
Materials must be stored in designated areas only	Material Storage	Medium	1	08 Jul, 16:31

This report was generated automatically by AeroInspect AI based on live site monitoring data.

Inspection Report

Generated 08 July 2026, 11:21 IST

Inspection Summary

Inspection Name	Zone D — Excavation Site (11:01 AM)
Workers Detected	13
Total Violations	3
Compliance Score	85.0%
Status	FLAGGED
Recorded	08 Jul 2026, 16:31 IST

Violation Breakdown

Category	Count
Helmet	1
Vest	0
Scaffolding	0
Debris	0
Restricted Zone	1
Fall Protection	0
Heavy Equipment	0
Unsafe Behaviour	0
Material Storage	1

Individual Violations

Violation	Category	Severity	Count	Time (IST)
Helmet is mandatory in all active work zones	Helmet	High	1	08 Jul, 16:31

No unauthorised entry into restricted zones	Restricted Zone	Critical	1	08 Jul, 16:31
Materials must be stored in designated areas only	Material Storage	Medium	1	08 Jul, 16:31

This report was generated automatically by AeroInspect AI based on live site monitoring data.