

AeroInspect AI — Inspection Report

Generated 10 July 2026, 23:54 IST

Inspection Summary

Inspection Name	Zone A Morning Sweep
Workers Detected	14
Total Violations	15
Compliance Score	25.0%
Status	unsafe
Recorded	04 Jul 2026, 22:41 IST

Violation Breakdown

Category	Count
Helmet	4
Vest	3
Scaffolding	2
Debris	0
Restricted Zone	0
Fall Protection	3
Heavy Equipment	1
Unsafe Behaviour	0
Material Storage	2

Individual Violations

Violation	Category	Severity	Count	Time (IST)
No Helmet	Helmet	High	2	04 Jul, 22:44
Unsecured Scaffold	Scaffolding	Medium	1	04 Jul, 22:44
Helmet is mandatory in all active work zones	Helmet	High	1	08 Jul, 04:14
Harness required for work above 2 metres	Fall Protection	Critical	1	08 Jul, 04:14

Minimum 3m distance from operating heavy equipment	Heavy Equipment	Critical	1	08 Jul, 16:28
High-visibility vest is mandatory in all active work zones	Vest	High	1	08 Jul, 16:28
High-visibility vest is mandatory in all active work zones	Vest	High	1	08 Jul, 16:28
Harness required for work above 2 metres	Fall Protection	Critical	1	08 Jul, 16:28
Scaffolding must be inspected and secured	Scaffolding	High	1	08 Jul, 16:28
Helmet is mandatory in all active work zones	Helmet	High	1	08 Jul, 16:28
High-visibility vest is mandatory in all active work zones	Vest	High	1	08 Jul, 16:28
Materials must be stored in designated areas only	Material Storage	Medium	1	08 Jul, 16:28
Harness required for work above 2 metres	Fall Protection	Critical	1	08 Jul, 16:28
Materials must be stored in designated areas only	Material Storage	Medium	1	08 Jul, 16:28

This report was generated automatically by AeroInspect AI based on live site monitoring data.