

AeroInspect AI — Inspection Report

Generated 08 July 2026, 19:49 IST

Inspection Summary

Inspection Name	East Wing (07:47 PM)
Workers Detected	8
Total Violations	1
Compliance Score	95.0%
Status	Safe
Recorded	09 Jul 2026, 01:17 IST

Violation Breakdown

Category	Count
Helmet	0
Vest	0
Scaffolding	0
Debris	0
Restricted Zone	0
Fall Protection	1
Heavy Equipment	0
Unsafe Behaviour	0
Material Storage	0

Individual Violations

Violation	Category	Severity	Count	Time (IST)
Harness required for work above 2 metres	Fall Protection	Critical	1	09 Jul, 01:17

This report was generated automatically by AeroInspect AI based on live site monitoring data.