

AeroInspect AI — Inspection Report

Generated 08 July 2026, 23:09 IST

Inspection Summary

Inspection Name	North Gate (07:51 PM)
Workers Detected	12
Total Violations	2
Compliance Score	90.0%
Status	Safe
Recorded	09 Jul 2026, 01:21 IST

Violation Breakdown

Category	Count
Helmet	1
Vest	1
Scaffolding	0
Debris	0
Restricted Zone	0
Fall Protection	0
Heavy Equipment	0
Unsafe Behaviour	0
Material Storage	0

Individual Violations

Violation	Category	Severity	Count	Time (IST)
Helmet is mandatory in all active work zones	Helmet	High	1	09 Jul, 01:21
High-visibility vest is mandatory in all active work zones	Vest	High	1	09 Jul, 01:21

This report was generated automatically by AeroInspect AI based on live site monitoring data.