

Ground Control Witness Form & Diagrams

Project Name: Dunrobin House

Date: 23/11/2023

Project Code: DUNR

	Details	Notes/Comments	Justification/Explanation
Survey Overview			
Date:		Date of survey	
Survey Conditions:	Clear, previous days of rain, bright sky	Brief description of survey conditions.	
No. of Points	6 Survey Targets (Thermal Targets) 6 Natural Points	Number of points being taken.	
Equipment:			
Model:	Leica FlexLine TS10	Make/model of surveying equipment used. This includes the make/model of any TST, prism, tripod	
Specifications:	Manual Total Station	Critical specifications only inc. accuracy, range etc.	
Additional Equipment	Leica GPR111 Prism Backsight	Equipment needed for the execution of the survey i.e. tape measure	
Survey Team:			
Planned / Set Up by:	Neil Sutherland	Lead individual responsible for survey planning	
Observed by:	Neil Sutherland	The individual taking the control point observations. This should remain consistent during the survey.	
Computed by:	Sean Ince	The team member responsible for the processing of the observations	

Notes:

Notes:


Positioned the TST laser on the 'T' of BT (the NON B Side)



Diagrams

Site Diagram 1:

1. Representation of station/marker locations in relation to subject



POINT 1

	Details	Notes/Comments	Justification/Explanation
Point Name:	P1	Name saved within the equipment	
Easting (X): (m)	997.111		
Northing (Y): (m)	1009.6704		
Height (Z): (m)	104.1154		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Used thermal-specific survey target as the marker, aligned onto T-crosshair between aluminium and rubber.

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

POINT 2

	Details	Notes/Comments	Justification/Explanation
Point Name:	P2	Name saved within the equipment	
Easting (X): (m)	999.892		
Northing (Y): (m)	1009.5859		
Height (Z): (m)	104.1069		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Used thermal-specific survey target as the marker, aligned onto T-crosshair between aluminium and rubber.

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

POINT 3

	Details	Notes/Comments	Justification/Explanation
Point Name:	P3	Name saved within the equipment	
Easting (X): (m)	1003.6426		
Northing (Y):	1009.4735		
Height (Z):	104.0804		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Used thermal-specific survey target as the marker, aligned onto T-crosshair between aluminium and rubber.

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

POINT 4

	Details	Notes/Comments	Justification/Explanation
Point Name:	P4	Name saved within the equipment	
Easting (X): (m)	1003.857		
Northing (Y):	1009.4746		
Height (Z):	101.4005		
CRS / Datum	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Used thermal-specific survey target as the marker, aligned onto T-crosshair between aluminium and rubber.

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

POINT 5

	Details	Notes/Comments	Justification/Explanation
Point Name:	P5	Name saved within the equipment	
Easting (X): (m)	999.2815		
Northing (Y): (m)	1009.6053		
Height (Z): (m)	101.3301		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Used thermal-specific survey target as the marker, aligned onto T-crosshair between aluminium and rubber.

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

POINT 6

	Details	Notes/Comments	Justification/Explanation
Point Name:	P6	Name saved within the equipment	
Easting (X): (m)	995.9992		
Northing (Y):	1009.7005		
Height (Z):	101.3318		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Used thermal-specific survey target as the marker, aligned onto T-crosshair between aluminium and rubber.

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point  A photograph of a red brick building. On the left, there is a white-framed window partially obscured by a large, dense green bush. In the center, a brick archway leads to a dark, narrow path that extends into the background. To the right of the archway, there is a white-framed bay window with multiple panes. Below the bay window, there are several smaller green bushes and a patch of grass. The overall scene is a residential garden area.

POINT 7

	Details	Notes/Comments	Justification/Explanation
Point Name:	P7	Name saved within the equipment	
Easting (X): (m)	997.2824		
Northing (Y):	1009.7146		
Height (Z):	105.0998		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Natural point Inside of top left window where glass meets frame (open in this window, closed in the survey) This allows point to be visible in both TST, RGB and TIR images

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point  A photograph of a two-story red brick building. The roof is covered in dark brown tiles and has two brick chimneys with copper-colored caps. A black downspout runs vertically down the left side of the building. On the left wall, there is a small circular window with a white frame. To the right of this, there are two white-framed rectangular windows, both of which are open. The sky is clear and blue.

POINT 8

	Details	Notes/Comments	Justification/Explanation
Point Name:	P8	Name saved within the equipment	
Easting (X): (m)	1000.0681		
Northing (Y):	1009.6307		
Height (Z):	105.1005		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Natural point Inside of central window unit, top left window where glass meets frame This allows point to be visible in both TST, RGB and TIR images

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

POINT 9

	Details	Notes/Comments	Justification/Explanation
Point Name:	P9	Name saved within the equipment	
Easting (X): (m)	1003.471		
Northing (Y):	1009.5302		
Height (Z):	105.1002		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Natural point Inside of right window unit, top right window where glass meets frame This allows point to be visible in both TST, RGB and TIR images

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point  A photograph of a red brick building with a dark tiled roof. The building features several white-framed windows, including a double window on the left and a single window on the right. A black downspout runs vertically along the right side of the building. A small white sign is mounted on the wall, reading "LORDS & SECURITY LTD". The sky is clear and blue.

POINT 10

	Details	Notes/Comments	Justification/Explanation
Point Name:	P10	Name saved within the equipment	
Easting (X): (m)	1003.6908		
Northing (Y):	1009.5286		
Height (Z):	102.3825		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Natural point Inside of bottom right window unit, top right of window where glass meets frame This allows point to be visible in both TST, RGB and TIR images

Diagrams Control Point Photo(s):	Contextual photo(s) of control point 
--	---

POINT 11

	Details	Notes/Comments	Justification/Explanation
Point Name:	P11	Name saved within the equipment	
Easting (X): (m)	997.3313		
Northing (Y):	1008.9079		
Height (Z):	102.396		
CRS / Datum:	LOCAL		
Station Name/No.:	N/A		

Notes:	
Notes:	Natural point Inside of top left window of the left central bay, where glass meets frame This allows point to be visible in both TST, RGB and TIR images

Diagrams	
Control Point Photo(s):	Contextual photo(s) of control point 

Diagrams	
Additional Images:	 A photograph of a light-colored building facade. On the left is a white door with a small window. To the right of the door is a window with three panes. Above the door and window are small, dark, rectangular objects, possibly vents or sensors. A small potted plant is visible near the base of the door. The image is somewhat blurry and has a warm, orange-toned lighting.



Diagrams

Additional Images:

