

=====

POLICE ACCIDENT & CRASH INVESTIGATION REPORT

=====

POLICE STATION: Johannesburg Central
CAS NUMBER: CAS 89/11/2023
OB NUMBER: OB 441/2023
REPORTING OFFICER: Constable M. Dlamini
BADGE NO: 88412

INCIDENT INFORMATION:

INCIDENT DATE: 2023-11-20
TIME: 08:45 AM
LOCATION: Corner Eloff & Marshall Street, Johannesburg CBD

DETAILS OF INCIDENT:

DESCRIPTION OF ACCIDENT:

Ford Ranger collided with rear end of Nissan NP200 at traffic signal.
The Nissan had come to a stationary stop at the red light when the Ford failed to maintain safe following distance due to wet road conditions.

VEHICLE & DAMAGE ASSESSMENT:

Vehicle A: Ford Ranger (Reg: BB 22 CC GP) - minor front bumper scratch.
Vehicle B: Nissan NP200 (Reg: DZ 44 KL GP) - tail light shattered, tailgate crumpled.
DAMAGES TO VEHICLE: Crumpled rear tailgate, shattered left tail light assembly.

STATUS: Claim documentation issued to insured parties for insurance submission.

=====