

Receiving Report

Report #::1-20-2018_11-18-09_AM_490011301.pdf

Order #:490011301**From:**

Marion Mold and Tool
176 Rifton Drive
exit 47, Interstate 81
10-20024
Marion
VA, 24354
US

Good's Quality**Good / Bad****Box Quality****Good / Bad****Packing Quality****Good / Bad****Part Description****Part #****Qty**

Granite Angle

0986

1

Lineal Granite 1200 x 200 x 60

0978

1

Sender:

Scott Russel / Sven Schonbach

Shipper**Steve Tunget****Ship Date:****5/1/2017 9:10:01 AM****starrag**