BCA Vehicle Appraisal Report

Grade 4


DV61 KJF, VAUXHALL CORSA

Registration: DV61 KJF	Colour: BLACK	Appraised: 25/10/2025
Transmission: Manual	Odometer: 118,069 miles	

Equipment

Air Conditioning	Alloy Wheels	Parking Sensor(s)
Privacy Glass		

Exterior condition



1. Bumper Rear; Cracked; Over 25mm
2. Bonnet; Dented; Over 30mm
3. Door osr; Dented; Over 30mm
4. Qtr Panel nsr; Dented; Over 30mm
5. Bonnet; Chipped; Multiple Chips
6. Qtr Panel nsr; Rusted; Over 5mm
7. Fogdriving Lamp nsf; Broken; Replace
8. Fogdriving Lamp osf; Broken; Replace
9. Bumper Rear; Insecure; Action Required
10. Bumper Front; Chipped; Multiple Chips
11. Door Mirror Assy nsf; Scratched (Painted); Over 25mm Thru Paint
12. Wheel nsf; Scratched; Over 50mm
13. Wheel nsr; Scratched; Over 50mm
14. Wheel osf; Scratched; Over 50mm
15. Wheel osr; Scratched; Up To 50mm
16. Door osf; Scratched; Over 25mm Not Thru Paint

Click to enlarge image






















Interior condition



1 Door Pad osf; Scuffed; Over 25mm

2 Seat Back Cover osf; Scuffed; Over 25mm

3 Tailgate Pad; Scuffed; Over 25mm

Click to enlarge image

