



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

KR67ZHM - SKODA KODIAQ SE TSI **NAMA** 2

VIN:	TMBKA7NS6J8043818		**Engine No:**	CZCA761414	
Transmission:	Manual	**Odometer:**	109414	**Reg Date:**	30/11/2017
Fuel Type:	Petrol	**Engine CC:**	1395	**Colour:**	WHITE
Body:	Estate	**Seats:**	7	**Spare Keys:**	1

Key Specification

Alloys	Parking sensors	AUX/USB	Radio/CD
Cruise control	Climate control	Air con	


Tyre Tread Depths

OSF	3.0	**OSR**	4.0	**NSF**	3.0	**NSR**	4.0
Spare		**Type**	None			**Run Flats**	0

Damage Details

	Wheel nsf	Scratched Up To 50mm	Smart Repair
1	**C Post os**	Scratched UpTo 25mm Thru Paint	Smart Repair
2	**Bonnet**	Scratched UpTo 25mm Thru Paint	Smart Repair
	Bonnet	Chipped 1 To 5	Report Only
	Bonnet	Previous Repair	Report Only
3	**Door osf**	Scratched UpTo 25mm Thru Paint	Smart Repair
4	**Wheel osr**	Scratched Over 50mm	Smart Repair
5	**Door osr**	Dented Over 30mm	Repair and Refinish
	Wing nsf	Previous Repair	Report Only
	Door nsf	Previous Repair	Report Only
	Bumper Front	Chipped 1 To 5	Smart Repair
	Door Mirror Assy nsf	Scratched (Painted) UpTo 25mm Thru Paint	Smart Repair
6	**Door nsr**	Dented Between 10mm + 30mm	Smart Repair

Sectional Damage Summary



Damage Images

1

C Post os

2

Bonnet

3

Door osf

4

Wheel osr

5

Door osr

6

Door nsr

Beauty Images


OSF


NSF


OSR



NSR


Dashboard


Additional


Interior


Load Area


OSR Interior

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	CF	**Date:**	17/10/2025