



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

LY73UYL - FORD PUMA ST-LINE MHEV **NAMA** 1

VIN:	WF02XXERK2PM38268		**Engine No:**	PM38268	
Transmission:	Manual	**Odometer:**	14280	**Reg Date:**	05/01/2024
Fuel Type:	Hybrid/Electric	**Engine CC:**	999	**Colour:**	WHITE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	1

Key Specification

Towbar	Alloys	Parking sensors	Heated windscreen
AUX/USB	Radio/CD	Cruise control	Air con
Sat nav			


Tyre Tread Depths

OSF	4.0	**OSR**	5.0	**NSF**	4.0	**NSR**	5.0
Spare		**Type**	None			**Run Flats**	0

Damage Details



●	**Screen Front**	Chipped UpTo 10mm	Smart Repair

Sectional Damage Summary



Damage Images

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Dashboard	 Additional	 Front Interior	 Rear Interior
 Load Area	 Additional		

Inspection Notes :			
Conditions:	Indoor	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RK	**Date:**	13/10/2025