



Vehicle Inspection Report

ASTON BARCLAY
Chelmsford

YF69FNL - SEAT LEON CUPRA 290 TSI **NAMA** 5

VIN:	VSSZZZ5FZLR027430		**Engine No:**	DNUC068314	
Transmission:	Automatic	**Odometer:**	75716	**Reg Date:**	25/11/2019
Fuel Type:	Petrol	**Engine CC:**	1984	**Colour:**	WHITE
Body:	Hatchback	**Seats:**	5	**Spare Keys:**	0

Key Specification

Alloys	Parking sensors	Air con	


Tyre Tread Depths

OSF	0.0	**OSR**	3.0	**NSF**	0.0	**NSR**	4.0
Spare		**Type**				**Run Flats**	0

Damage Details


1	**Sill Panel Trim os**	Scuffed (Unpainted) UpTo 100mm	Smart Repair
2	**Wheel nsr**	Scratched Up To 50mm	Smart Repair
3	**Wheel osr**	Scratched Over 50mm	Smart Repair
4	**Tyre nsf**	Punctured Replace	Replace
5	**Tyre osf**	Damaged Replace	Replace
6	**Wing osf**	Dented With Paint Damage	Repair and Refinish
7	**Wheel nsf**	Scratched Over 50mm	Smart Repair
8	**Wheel osf**	Scratched Over 50mm	Smart Repair
9	**Roof**	Dented 2 Or Less UpTo 10mm	Smart Repair
10	**Roof**	Chipped 1 To 5	Report Only
11	**Bonnet**	Dented With Paint Damage	Repair and Refinish
12	**Door osf**	Dented Over 30mm	Repair and Refinish
13	**Bumper Rear**	Cracked Over 25mm	Replace
14	**Lamp nsr**	Broken Replace	Replace
15	**Tailgate**	Dented With Paint Damage	Repair and Refinish
16	**Seat Base Cover nsf**	Soiled Light	Clean

Sectional Damage Summary



17	**Qtr Panel nsr**	Dented Over 30mm	Repair and Refinish
18	**Tailgate Pad**	Scuffed Over 25mm	Smart Repair
19	**Screen Front**	Cracked Replace	Replace
20	**Bumper Front**	Hole Over 25mm	Replace

Damage Images

1

Sill Panel Trim os

2


Wheel nsr

3

Wheel osr

4

Tyre nsf

4

Tyre nsf

5

Tyre osf

6

Wing osf

6

Wing osf

7

Wheel nsf

8



Wheel osf

9



Roof

10

Roof

11  Bonnet	12  Door osf	13  Bumper Rear	14  Lamp nsr
15  Tailgate	15  Tailgate	16  Seat Base Cover nsf	17  Qtr Panel nsr
18  Tailgate Pad	19  Screen Front	20  Bumper Front	

Beauty Images

 OSF	 NSF	 OSR	 NSR
 Speedometer	 Interior	 OSR Interior	 Dashboard
 Boot			

Inspection Notes :			
Conditions:	Dry	**Location:**	Aston Barclay Chelmsford
Inspector's Name:	RB	**Date:**	21/10/2025