

Electrical Safety Inspection

Inspection Date: 13 September 2026
Facility: Manufacturing Plant B
Inspection Type: Routine Electrical Safety Inspection

1. Executive Summary

A routine inspection was conducted to assess electrical panels, wiring, warning labels, grounding arrangements, and general workplace electrical safety. Several labeling and housekeeping issues were identified and require corrective action.

2. Electrical Equipment Condition

Distribution panels were operational and generally in serviceable condition. One panel door was not closing securely and should be repaired. Cable routing near the maintenance area requires better organization.

3. Safety Violations

Two issues were observed: an electrical access area was partially obstructed by stored material, and one panel lacked an updated hazard warning label.

4. Electrical Observations

No exposed live conductors were observed during the inspection. Grounding connections appeared intact at the inspected points. The panel-door defect should be corrected before the next scheduled maintenance activity.

5. Corrective Actions

Clear the electrical access area, replace the missing hazard label, repair the panel door, and reorganize cables in the maintenance area. Document completion of each action.

6. Inspector Recommendation

A follow-up inspection should be completed within 14 days. Electrical access routes should remain clear at all times.

Inspection Findings Summary

Finding	Priority	Recommended Action
Obstructed electrical access	High	Clear immediately
Missing hazard label	Medium	Replace label
Loose panel door	Medium	Repair and inspect
Poor cable organization	Low	Re-route cables