

Warehouse Safety Inspection

Inspection Date: 13 September 2026
Facility: Central Warehouse E
Inspection Type: Routine Warehouse Safety Inspection

1. Executive Summary

A routine warehouse inspection was conducted to assess material storage, aisle clearance, equipment condition, emergency access, signage, and housekeeping. The warehouse was generally orderly, with several observations requiring attention.

2. Storage Condition

Most materials were stored securely. One pallet was positioned close to an aisle boundary and should be relocated to maintain clear access.

3. Safety Violations

A fire-extinguisher access zone was partially obstructed by packaging material. One storage-area warning sign was damaged.

4. Access and Housekeeping Observations

Main walkways were generally clear. Packaging waste was present near the loading area and should be removed at the end of the shift.

5. Corrective Actions

Relocate the pallet, clear the fire-equipment access zone, replace the damaged warning sign, and remove packaging waste.

6. Inspector Recommendation

Supervisors should verify aisle and emergency-equipment clearance during daily warehouse checks.

Inspection Findings Summary

Finding	Priority	Recommended Action
Obstructed fire-equipment access	High	Clear immediately
Pallet near aisle boundary	Medium	Relocate pallet
Damaged warning sign	Low	Replace sign
Packaging waste	Low	Remove and clean