FRONT CRUISER

OSM Thome

WEEKLY MAINTENANCE PHOTOS– WEEK 52
28-DEC-2025 TO 03-JAN-2025

Greasing of mooring wires



Greasing of mooring wires

Greasing of mooring wires

Greasing of mooring wires

FRONT CRUISER

OSM Thome

WEEKLY MAINTENANCE PHOTOS– WEEK 52

28-DEC-2025 TO 03-JAN-2025



Greasing of mooring wires

Greasing of mooring wires

Greasing of mooring wires

Greasing of mooring wires

OSM Thome

WEEKLY MAINTENANCE PHOTOS– WEEK 52

28-DEC-2025 TO 03-JAN-2025

Greasing of mooring wires

Greasing of mooring wires

Greasing of mooring wires

Greasing of mooring wires

OSM Thome

WEEKLY MAINTENANCE PHOTOS– WEEK 52

28-DEC-2025 TO 03-JAN-2025

De-rusting on Flanges and various areas of IG line and its valves

De-rusting on Flanges and various areas of IG line and its valves

De-rusting on Flanges and various areas of IG line and its valves

De-rusting on Flanges and various areas of IG line and its valves

WEEKLY MAINTENANCE PHOTOS– WEEK 52

28-DEC-2025 TO 03-JAN-2025

De-rusting on Flanges and various areas of IG line and its valves

De-rusting on Flanges and various areas of IG line and its valves

De-rusting on Flanges and various areas of IG line and its valves

De-rusting on Flanges and various areas of IG line and its valves

OSM Thome

WEEKLY MAINTENANCE PHOTOS– WEEK 52

28-DEC-2025 TO 03-JAN-2025

Primer application on de-rusted areas of IG line, its flanges, spool piece and platform



Primer application on de-rusted areas of IG line, its flanges, spool piece and platform

Primer application on de-rusted areas of IG line, its flanges, spool piece and platform

Primer application on de-rusted areas of IG line, its flanges, spool piece and platform

Inspection of IG line NRV

Inspection of IG line NRV

Inspection of IG line NRV

Inspection of IG line NRV

OSM Thome

WEEKLY MAINTENANCE PHOTOS– WEEK 52

28-DEC-2025 TO 03-JAN-2025

Cleaning main deck and fish plates

Cleaning main deck and fish plates

Cleaning main deck and fish plates

Cleaning main deck and fish plates