AI Car Damage Inspection Report

Report ID: 10d0b463-f1f | **Timestamp:** 2026-11-02 09:21:54 UTC

Inspection Verdict	DAMAGED	**Confidence Score**	65.2%
Estimated Severity	SEVERE	**Damaged Area Ratio**	3.60%
Needs Human Review	NO (Auto Pass)	**Pipeline Latency**	326.4 ms

Visual Inspection (Original vs. AI Annotated Detections)



Original Vehicle Photo



Annotated Damage Localization (YOLO11)

Localized Damage Regions

#	Damage Class	Confidence	Bounding Box [x1, y1, x2, y2]
1	severe_replace	48.5%	[579.4, 327.4, 806.6, 451.9]
2	scratch	23.9%	[652.3, 312.0, 752.8, 372.3]

Disclaimer: This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.