AI Car Damage Inspection Report

Report ID: 75047387-c11 | **Timestamp:** 2026-11-02 09:22:46 UTC

Inspection Verdict	UNDAMAGED	**Confidence Score**	94.2%
Estimated Severity	NONE	**Damaged Area Ratio**	0.00%
Needs Human Review	NO (Auto Pass)	**Pipeline Latency**	46.7 ms

Visual Inspection (Original vs. AI Annotated Detections)



Original Vehicle Photo



Annotated Damage Localization (YOLO11)

Localized Damage Regions

No localized bounding-box detections above threshold.

Disclaimer: This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.