AI Car Damage Inspection Report

Report ID: 97dee4dc-92d | **Timestamp:** 2026-11-02 09:23:36 UTC

Inspection Verdict	DAMAGED	**Confidence Score**	57.9%
Estimated Severity	SEVERE	**Damaged Area Ratio**	38.56%
Needs Human Review	NO (Auto Pass)	**Pipeline Latency**	153.4 ms

Visual Inspection (Original vs. AI Annotated Detections)



Original Vehicle Photo



Annotated Damage Localization (YOLO11)

Localized Damage Regions

#	Damage Class	Confidence	Bounding Box [x1, y1, x2, y2]
1	severe_replace	52.3%	[23.2, 172.3, 472.3, 359.2]
2	severe_replace	22.5%	[211.6, 163.5, 632.1, 347.8]

Disclaimer: This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.