# AI Car Damage Inspection Report

**Report ID:** bead92ef-1a2 | **Timestamp:** 2026-11-02 09:09:58 UTC

| | | | |
|---|---|---|---|
| **Inspection Verdict** | DAMAGED | **Confidence Score** | 10.0% |
| **Estimated Severity** | MINOR | **Damaged Area Ratio** | 0.00% |
| **Needs Human Review** | YES (Human Triage Recommended) | **Pipeline Latency** | 587.3 ms |

### *Visual Inspection (Original vs. AI Annotated Detections)*



*Original Vehicle Photo*



*Annotated Damage Localization (YOLO11)*

### *Localized Damage Regions*

No localized bounding-box detections above threshold.

**Disclaimer:** This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.