# AI Car Damage Inspection Report

**Report ID:** c96094fd-05c | **Timestamp:** 2026-11-02 09:31:41 UTC

| | | | |
|---|---|---|---|
| **Inspection Verdict** | UNDAMAGED | **Confidence Score** | 89.9% |
| **Estimated Severity** | NONE | **Damaged Area Ratio** | 0.00% |
| **Needs Human Review** | NO (Auto Pass) | **Pipeline Latency** | 378.1 ms |

## *Visual Inspection (Original vs. AI Annotated Detections)*




*Original Vehicle Photo*




*Annotated Damage Localization (YOLO11)*

## *Localized Damage Regions*

No localized bounding-box detections above threshold.

**Disclaimer:** This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.