AI Car Damage Inspection Report

Report ID: e8686bf5-01f | **Timestamp:** 2026-11-02 08:59:40 UTC

Inspection Verdict	DAMAGED	**Confidence Score**	13.5%
Estimated Severity	SEVERE	**Damaged Area Ratio**	17.08%
Needs Human Review	YES (Human Triage Recommended)	**Pipeline Latency**	403.1 ms

Visual Inspection (Original vs. AI Annotated Detections)



Original Vehicle Photo



Annotated Damage Localization (YOLO11)

Localized Damage Regions

#	Damage Class	Confidence	Bounding Box [x1, y1, x2, y2]
1	severe_replace	40.9%	[875.6, 1630.9, 3081.0, 2430.6]
2	scratch	17.9%	[959.8, 1392.5, 1477.7, 1847.3]

Disclaimer: This report was generated automatically by the AI Car Damage Inspection System (ConvNeXt-Tiny Classifier + YOLO11 Detector + Calibrated Severity Heuristic). Severity scores are calibrated estimates for insurance claims triage and rental return checks, not a certified structural repair quote.