





pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 11_12 — halves could not be aligned — shown as measured





pure 11_21 — halves could not be aligned — shown as measured





pure 11_22 — halves could not be aligned — shown as measured



pure 12_13 — halves could not be aligned — shown as measured



pure 12_21 — aligned: $-V \approx \pm(+V)(0.96 \cdot w + 264)$, $r=0.89$





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 12_22 — halves could not be aligned — shown as measured





pure 12_23 — aligned: $-V \approx \pm(+V)(1.10 \cdot w + 48)$, $r=0.87$





pure 13_14 — halves could not be aligned — shown as measured



pure 13_22 — halves could not be aligned — shown as measured



pure 13_23 — aligned: $-V \approx \pm(+V)(1.03 \cdot w + 32)$, $r=0.93$





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 13_24 — aligned: $-V \approx \pm(+V)(1.07 \cdot w + 0)$, $r=0.94$





pure 14_23 — halves could not be aligned — shown as measured





pure 14_24 — halves could not be aligned — shown as measured



pure 21_22 — aligned: $-V \approx \pm(+V)(0.90 \cdot w + 192)$, $r=0.85$



pure 21_31 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 21_32 — aligned: $-V \approx \pm(+V)(0.87 \cdot w + 224)$, $r=0.89$





pure 22_23 — halves could not be aligned — shown as measured





pure 22_31 — aligned: $-V \approx \pm(+V)(1.00 \cdot w + 32)$, $r=0.94$



pure 22_32 — halves could not be aligned — shown as measured



pure 22_33 — aligned: $-V \approx \pm(+V)(1.01 \cdot w + 104)$, $r=0.88$





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 23_24 — halves could not be aligned — shown as measured





pure 23_32 — aligned: $-V \approx \pm(+V)(0.95 \cdot w + 120)$, $r=0.92$





pure 23_33 — halves could not be aligned — shown as measured



pure 23_34 — halves could not be aligned — shown as measured



pure 24_33 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 24_34 — halves could not be aligned — shown as measured





pure 31_32 — halves could not be aligned — shown as measured





pure 31_41 — aligned: $-V \approx \pm(+V)(1.06 \cdot w + 64)$, $r=0.84$



pure 31_42 — aligned: $-V \approx \pm(+V)(1.01 \cdot w + 160)$, $r=0.90$



pure 32_33 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 32_41 — halves could not be aligned — shown as measured





pure 32_42 — halves could not be aligned — shown as measured





pure 32_43 — halves could not be aligned — shown as measured



pure 33_34 — halves could not be aligned — shown as measured



pure 33_42 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 33_43 — halves could not be aligned — shown as measured





pure 33_44 — halves could not be aligned — shown as measured





pure 34_43 — halves could not be aligned — shown as measured



pure 34_44 — halves could not be aligned — shown as measured



pure 41_42 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 41_51 — aligned: $-V \approx \pm(+V)(1.13 \cdot w + 24)$, $r=0.90$





pure 41_52 — aligned: $-V \approx \pm(+V)(1.03 \cdot w + 56)$, $r=0.90$





pure 42_43 — halves could not be aligned — shown as measured



pure 42_51 — halves could not be aligned — shown as measured



pure 42_52 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 42_53 — aligned: $-V \approx \pm(+V)(0.95 \cdot w + 32)$, $r=0.86$





pure 43_44 — halves could not be aligned — shown as measured





pure 43_52 — halves could not be aligned — shown as measured



pure 43_53 — halves could not be aligned — shown as measured



pure 43_54 — halves could not be aligned — shown as measured





Wavenumber, common axis (cm⁻¹)



Wavenumber, common axis (cm⁻¹)

pure device — left: raw (before), right: denoised (after). Lines: solid = confirmed in both halves, dashed = strong single-half, dotted = tentative



pure 44_53 — halves could not be aligned — shown as measured





pure 44_54 — halves could not be aligned — shown as measured





pure 51_52 — halves could not be aligned — shown as measured



pure 52_53 — aligned: $-V \approx \pm(+V)(1.00 \cdot w - 352)$, $r=0.85$



pure 53_54 — halves could not be aligned — shown as measured [nearly identical data in both device folders]



Wavenumber, common axis (cm⁻¹)

Wavenumber, common axis (cm⁻¹)