FLOODLENS AI · LIVE · Deterministic evidence-backed report

Flood situation report

Trishuli river corridor · 2026-08-26

Generated: 2026-10-14T14:54:51+00:00

Run 0fb99632-2943-4d03-9656-55f1db0682cd · Report d714a52a-6ea6-4efb-a252-2c47a3b8b949

INCOMPLETE REPORT — partial observations. Unavailable measurements are not zero. Processed optical acquisition dates, Possible surface/debris change

Satellite observations

Before radar acquisition: 2026-08-16T12:21:41.058298Z

After radar acquisition: 2026-08-28T12:21:41.762029Z

Processed optical product IDs: No entries recorded

Processed optical acquisition dates: Unavailable

Flood and surface-change findings

Potential new inundation: 0.000 km²

Possible surface/debris change: Unavailable

Pre-existing water: 0.701 km²

Eligible observation coverage: 13.6 %

Paired clear optical coverage: 0.0 %

Water-class eligible coverage: 13.6 %

Surface-change-class eligible coverage: 0.0 %

Surface-change/debris candidates can include other land-cover changes; they are not confirmed debris flows.

Unobserved areas remain unknown. No mapped change does not prove absence of damage.

Potential infrastructure exposure

Potentially exposed buildings: 0

Potentially exposed road features: 0

Potentially exposed bridges: 0

Road length intersecting mapped changes: 0.000 km

Mapped intersection indicates potential exposure, not confirmed damage or destruction.

Modeled settlement connectivity

Settlements with modeled loss of access: 0

Unassessed settlements: 56

Settlements with uncertain access: 47

Already disconnected settlements: 6

Connectivity assumes candidate-intersecting road segments are impassable. Actual closures and physical inaccessibility are unverified.

Sources and evidence

Before radar product id: S1D_IW_GRDH_1SDV_20260816T122141_20260816T122206_004151_007980_B091_COG

After radar product id: S1D_IW_GRDH_1SDV_20260828T122141_20260828T122206_004326_007FA4_C73B_COG

Historical OSM snapshot: 2026-07-27T08:59:58Z

Detection method: Rule-based radar and optical change detection

Evidence: result.json, extent.geojson and the selected analysis’s infrastructure/connectivity layers.

Important limitations

Satellite revisit gaps, terrain shadow, clouds and vegetation limit interpretation; the system cannot provide minute-ahead warnings.

Incomplete OSM roads, facility operation and routes outside the analysis bounds remain unverified.

Unobserved areas remain unknown. No mapped change does not prove absence of damage.

Population and casualty estimates are unavailable. Field verification and native-speaker Nepali review remain necessary.

Contains modified Copernicus Sentinel data 2026.
Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
© OpenStreetMap contributors.
Educational prototype; independent field verification required.