

Date & Time:  
**29-06-2021**  
**12:19**

Driver:  
**Olaf**  
**Noordegraaf**

Vehicle  
Number:  
**XLRTEH4300G**  
**224957**

Licence Plate:

Vehicle Name:  
**Test**

Trailer Number:  
**0**

Mileage (kms):  
**0**

Sr.	Category	Defects
1	Lights and indicators	✓
2	Height marker	✓
3	Windscreen wipers and washers	✓
4	Dashboard warning lights and gauges	✓
5	Tachograph	✓
6	Brake lines and trailer parking brake	✓
7	Engine exhaust	✓
8	Fuel and oil leaks	✓
9	Coupling security	✓
10	Battery security and conditions	✓
11	Security of body and wings	✓
12	Spray suppression	✓
13	Tyres and wheel fixing	✓
14	Reflectors	✓
15	Markings and warning plates	✓
16	Number plate	✓
17	Doors	✓
18	Load	✓
19	Electrical connections	✓
20	Truck Damage	✓
21	Steering	✓

Sr.	Category	Defects
22	Mirrors	✓
23	Front view	✓
24	Seatbelts	✓
25	Seats	✓
26	Brakes	✓
27	Horn	✓
28	Pedals	⚠ 3
29	Diesel exhaust fluid (AdBlue)	✓

Details Of Defects -

1 Pedals

Defect Details:

- 1.1 The pedal is not working properly
- 1.2 Brake pedal rubber has cracks or is party missing
- 1.3 Clutch pedal rubber has cracks or is party missing

Description:

NA

Photos:

NA