


Manhattan, uninhabited

Habitability after infrastructural collapse — neighborhood survey



 Inundated  Critical  Severe  Degraded  Marginal  Parkland

A Aqueduct terminus

B Subway pump network

C East River station

D Newtown Creek works

E Hunts Point market

F Astoria power plants

G Holland and Lincoln shafts

 Severed crossings