Organizations

Org ID	Organization Name	Type	Address	Contact Email	Contact Number	Status
1	National Highways Authority of India	ROAD_AUTHORITY	New Delhi, India	contact@nha-demo.example	+91-11-4000-1001	ACTIVE
2	Bharat Roadworks Infrastructure Ltd	CONTRACTOR	Mumbai, India	projects@bharatroad-demo.example	+91-22-4000-1002	ACTIVE
3	RoadSure Assurance Ltd	INSURANCE_COMPANY	Bengaluru, India	underwriting@roadsure-demo.example	+91-80-4000-1003	ACTIVE
4	GeoPave Inspection Services	INSPECTION_ORGANIZATION	Pune, India	inspections@geopave-demo.example	+91-20-4000-1004	ACTIVE
5	Coastal Civil Engineering Pvt Ltd	CONTRACTOR	Chennai, India	delivery@coastalcivil-demo.example	+91-44-4000-1005	ACTIVE
6	MetroLink Infrastructure JV	CONTRACTOR	Hyderabad, India	roads@metrolink-demo.example	+91-40-4000-1006	ACTIVE
7	Western Corridor Authority	ROAD_AUTHORITY	Ahmedabad, India	projects@wca-demo.example	+91-79-4000-1007	ACTIVE
8	Apex Materials Testing	INSPECTION_ORGANIZATION	Jaipur, India	lab@apexmaterials-demo.example	+91-141-4000-1008	ACTIVE
9	Global Pavement Underwriters	INSURANCE_COMPANY	Singapore	risk@gpu-demo.example	+65-6000-1009	ACTIVE
10	Andes Road Engineering	CONTRACTOR	Lima, Peru	works@andesroad-demo.example	+51-1-600-1010	ACTIVE

Users and Roles

Passwords and password hashes are not included. Contact details use reserved demo domains and fictional telephone numbers.

User ID	Org ID	Name	Email	Role	Status
1	3	Mira Shah	mira.admin@roadsure-demo.example	ADMIN	ACTIVE
2	1	Arjun Mehta	arjun.authority@roadsure-demo.example	ROAD_AUTHORITY_PM	ACTIVE
3	2	Kavya Rao	kavya.contractor@roadsure-demo.example	CONTRACTOR_PM	ACTIVE
4	4	Dev Malhotra	dev.inspector@roadsure-demo.example	INSPECTOR	ACTIVE
5	3	Nisha Iyer	nisha.underwriter@roadsure-demo.example	UNDERWRITER	ACTIVE
6	3	Rohan Kapoor	rohan.adjuster@roadsure-demo.example	CLAIMS_ADJUSTER	ACTIVE
7	5	Sana Fernandes	sana.coastal@roadsure-demo.example	CONTRACTOR_PM	ACTIVE
8	6	Ishaan Reddy	ishaan.metro@roadsure-demo.example	CONTRACTOR_PM	ACTIVE
9	7	Priya Desai	priya.wca@roadsure-demo.example	ROAD_AUTHORITY_PM	ACTIVE
10	8	Rahul Bansal	rahul.apex@roadsure-demo.example	INSPECTOR	ACTIVE
11	9	Ethan Lim	ethan.uw@roadsure-demo.example	UNDERWRITER	ACTIVE
12	10	Lucia Torres	lucia.andes@roadsure-demo.example	CONTRACTOR_PM	ACTIVE

Road Projects

Project ID	Project Name	Location	Length km	Estimated Cost INR	Lifespan yrs	Status	Authority Org ID	Contractor Org ID	Start Date	Expected Completion	Project Description
1	Delhi–Jaipur Freight Corridor Upgrade	Delhi–Jaipur, India	268	6850000000	30	UNDER_CONSTRUCTION	1	2	2025-04-15	2027-12-31	Widening for freight traffic; asph strengthening
2	Mumbai Coastal Road Resilience Section	Mumbai, India	18.5	21400000000	40	FINAL_INSPECTION_PENDING	1	5	2023-10-01	2026-12-15	Coastal protection, drainage an
3	Hyderabad Outer Ring Road Drainage Renewal	Hyderabad, India	42	1260000000	25	UNDER_CONSTRUCTION	1	6	2026-01-12	2027-08-30	Drainage rehabilitation and aspl
4	Bengaluru Airport Access Corridor	Bengaluru, India	31	3180000000	30	COMPLETED	1	2	2024-02-01	2026-06-30	High-volume airport access roa layers
5	Pune–Satara Highway Pavement Rehabilitation	Pune–Satara, India	57	2470000000	25	FINAL_INSPECTION_PENDING	1	2	2025-07-10	2027-03-31	Milling, overlay, shoulder repair

Project ID	Project Name	Location	Length km	Estimated Cost INR	Lifespan yrs	Status	Authority Org ID	Contractor Org ID	Start Date	Expected Completion	Project Description
6	Ahmedabad Ring Road Heavy-Vehicle Segment	Ahmedabad, India	24	1960000000	30	UNDER_CONSTRUCTION	7	6	2025-11-01	2027-05-31	Heavy axle-load pavement and
7	Chennai–Mahabalipuram Coastal Highway Renewal	Chennai, India	36	1730000000	25	UNDER_CONSTRUCTION	1	5	2025-06-01	2027-09-30	Coastal asphalt renewal with sa controls
8	Jaipur Urban Arterial Resurfacing Package	Jaipur, India	22	845000000	20	COMPLETED	7	2	2024-08-15	2026-05-30	Urban resurfacing, utility-cover a repairs
9	Guwahati Flood-Resilient Bypass	Guwahati, India	29	2310000000	30	READY_FOR_ASSESSMENT	1	6	2026-03-01	2028-02-28	Raised sections, culvert upgrad drainage
10	Kochi Port Container Access Road	Kochi, India	16	1580000000	25	UNDER_CONSTRUCTION	1	5	2025-09-01	2027-04-30	Port traffic pavement designed f
11	Nagpur Concrete Bypass Renewal	Nagpur, India	34	2890000000	35	COMPLETED	1	2	2023-05-01	2026-02-28	Concrete pavement panels, join improvements
12	Dehradun Hill-Slope Road Stabilisation	Dehradun, India	19	1420000000	25	UNDER_CONSTRUCTION	1	6	2025-10-15	2027-11-30	Slope stabilisation, erosion cont
13	Lima Pan-American Highway Surface Renewal	Lima, Peru	44	980000000	20	FINAL_INSPECTION_PENDING	7	10	2025-02-01	2026-11-30	Surface renewal for mixed urba
14	Singapore East Connector Pavement Renewal	Singapore	12	720000000	20	DETAILS_SUBMITTED	7	10	2026-08-01	2027-10-31	Pavement renewal, stormwater management
15	Visakhapatnam Industrial Access Road	Visakhapatnam, India	26	1330000000	25	CREATED	1	5	2026-10-01	2028-01-31	Industrial access road with drain controls

Construction Details

Project ID	Methodology	Material Type	Timeline	Equipment Details	Workforce Details
1	Survey and traffic staging; subgrade improvement; granular base; asphalt binder and wearing courses; compaction; shoulder strengthening; acceptance testing.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
2	Coastal exposure survey; pavement milling; corrosion-resistant drainage fixtures; polymer-modified asphalt; compaction and surface-friction testing.	Polymer-modified asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
3	Drain inspection; culvert cleaning; subgrade repair; asphalt resurfacing; compaction; post-rainfall drainage verification.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
4	Base-layer strengthening; asphalt paving; density checks; lane marking; final ride-quality and drainage checks.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
5	Milling; patching; tack coat; asphalt overlay; shoulder repair; compaction and core sampling.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
6	Heavy-load pavement design; subgrade stabilisation; thick asphalt courses; junction strengthening; axle-load inspection.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
7	Coastal-condition material selection; surface milling; asphalt overlay; drainage outlets; salt-exposure monitoring.	Polymer-modified asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
8	Night-shift milling and resurfacing; utility-cover adjustment; compaction; road-marking and ride-quality checks.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
9	Culvert replacement; raised embankment sections; subgrade stabilisation; asphalt paving; flood-flow verification.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
10	Heavy-duty base; asphalt binder and surface layers; turning-radius reinforcement; drainage and rutting checks.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
11	Concrete panel repair; joint resealing; dowel inspection; drainage improvements; surface-friction tests.	Concrete	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
12	Slope drainage; retaining structures; erosion protection; local pavement reconstruction; geotechnical and compaction checks.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
13	Surface milling; asphalt overlay; crack sealing; traffic staging; compaction and skid-resistance checks.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts
14	Pavement milling; new wearing course; stormwater inlet upgrades; night traffic management; smoothness tests.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts

Project ID	Methodology	Material Type	Timeline	Equipment Details	Workforce Details
15	Subgrade survey; granular base; asphalt courses; roadside drainage; heavy-vehicle turning-area reinforcement.	Dense-graded asphalt	18–32 months	Paver, tandem roller, grader, excavator, compactor and testing equipment	120–420 workers across shifts

Construction Progress

Progress ID	Project ID	Progress %	Work Description	Progress Date	Created By User ID
1	1	67	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	8
2	2	96	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	2
3	3	67	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	12
4	4	100	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-06-30	12
5	5	96	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	2
6	6	38	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	2
7	7	81	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	2
8	8	100	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-05-30	8
9	9	18	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	3
10	10	54	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	3
11	11	100	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-02-28	7
12	12	54	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	2
13	13	96	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	3
14	14	8	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-12	8
15	15	0	Work packages completed to the current reported stage; progress is a generated project snapshot.	2026-10-01	7

Inspection History

Failed inspections and rejected approvals are intentionally retained so retrieval can compare failures, corrective actions, and later outcomes.

Inspection ID	Type	Project ID	Inspection Date	Material Score	Thickness Score	Test Score	Remarks	Inspection Status	Approval Status	Inspector User ID
1	INITIAL	1	2026-03-06	86	96	86	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
2	PERIODIC	1	2026-07-06	49	55	59	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	4
3	FINAL	1	2026-11-06	89	72	83	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
4	INITIAL	2	2025-03-07	78	78	92	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
5	PERIODIC	2	2025-07-07	44	59	53	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	10
6	FINAL	2	2025-11-07	82	92	78	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	PENDING	10
7	INITIAL	3	2026-03-08	91	93	91	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
8	PERIODIC	3	2026-07-08	62	77	43	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	4
9	FINAL	3	2026-11-08	81	88	88	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
10	INITIAL	4	2025-03-09	90	92	93	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
11	PERIODIC	4	2025-07-09	82	87	90	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
12	FINAL	4	2025-11-09	90	96	90	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
13	INITIAL	5	2026-03-10	91	96	78	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
14	PERIODIC	5	2026-07-10	44	73	66	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	4
15	FINAL	5	2026-11-10	91	87	92	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	PENDING	10
16	INITIAL	6	2025-03-11	88	80	84	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
17	PERIODIC	6	2025-07-11	40	55	42	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	4
18	FINAL	6	2025-11-11	81	95	83	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
19	INITIAL	7	2026-03-12	82	90	91	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
20	PERIODIC	7	2026-07-12	59	71	62	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	10
21	FINAL	7	2026-11-12	77	91	86	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
22	INITIAL	8	2025-03-13	94	96	94	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
23	PERIODIC	8	2025-07-13	77	74	78	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
24	FINAL	8	2025-11-13	92	77	75	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4

Inspection ID	Type	Project ID	Inspection Date	Material Score	Thickness Score	Test Score	Remarks	Inspection Status	Approval Status	Inspector User ID
25	INITIAL	9	2026-03-14	86	78	92	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
26	PERIODIC	9	2026-07-14	52	69	42	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	10
27	FINAL	9	2026-11-14	93	89	87	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	PENDING	10
28	INITIAL	10	2025-03-15	93	76	88	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
29	PERIODIC	10	2025-07-15	49	70	43	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	10
30	FINAL	10	2025-11-15	82	85	80	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
31	INITIAL	11	2026-03-16	84	94	83	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
32	PERIODIC	11	2026-07-16	79	84	81	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
33	FINAL	11	2026-11-16	91	92	84	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
34	INITIAL	12	2025-03-17	78	93	80	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
35	PERIODIC	12	2025-07-17	64	74	47	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	10
36	FINAL	12	2025-11-17	76	73	75	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
37	INITIAL	13	2026-03-18	92	85	93	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
38	PERIODIC	13	2026-07-18	55	67	41	Material density or mix compliance below acceptance threshold; corrective work and reinspection required.	FAILED	REJECTED	10
39	FINAL	13	2026-11-18	96	78	96	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	PENDING	10
40	INITIAL	14	2025-03-19	96	76	90	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4
41	PERIODIC	14	2025-07-19	94	92	80	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
42	FINAL	14	2025-11-19	91	93	81	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
43	INITIAL	15	2026-03-20	80	94	91	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
44	PERIODIC	15	2026-07-20	82	77	92	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	10
45	FINAL	15	2026-11-20	87	87	80	Field measurements and laboratory tests within the inspection acceptance range.	PASSED	APPROVED	4

Defects

Defect ID	Project ID	Inspection ID	Defect Type	Description	Status
1	1	2	Layer Thickness Issue	Core samples show local pavement layer thickness below the project specification.	RESOLVED
2	2	5	Drainage Damage	Standing water and restricted flow observed at roadside drainage inlets.	CORRECTIVE_ACTION_SUBMITTED
3	3	8	Surface Failure	Ravelling and loss of aggregate observed in the wearing course.	RESOLVED

Defect ID	Project ID	Inspection ID	Defect Type	Description	Status
4	5	14	Cracking	Longitudinal and transverse cracks observed near wheel paths.	RESOLVED
5	6	17	Rutting	Wheel-path deformation observed under repeated heavy vehicle loading.	CORRECTIVE_ACTION_SUBMITTED
6	7	20	Potholes	Potholes observed after rainfall; patch boundaries require proper preparation.	RESOLVED
7	9	26	Drainage Damage	Standing water and restricted flow observed at roadside drainage inlets.	CORRECTIVE_ACTION_SUBMITTED
8	10	29	Rutting	Wheel-path deformation observed under repeated heavy vehicle loading.	RESOLVED
9	12	35	Erosion	Shoulder erosion observed near a sloped embankment.	OPEN
10	13	38	Cracking	Longitudinal and transverse cracks observed near wheel paths.	CORRECTIVE_ACTION_SUBMITTED

Corrective Actions

Action ID	Defect ID	Action Taken	Verification Status	Updated Date
1	1	Affected section milled and resurfaced; compaction and core samples scheduled for verification.	VERIFIED	2026-10-14
2	2	Contractor submitted repair plan; verification inspection pending.	PENDING	2026-10-14
3	3	Affected section milled and resurfaced; compaction and core samples scheduled for verification.	VERIFIED	2026-10-14
4	4	Affected section milled and resurfaced; compaction and core samples scheduled for verification.	VERIFIED	2026-10-14
5	5	Contractor submitted repair plan; verification inspection pending.	PENDING	2026-10-14
6	6	Affected section milled and resurfaced; compaction and core samples scheduled for verification.	VERIFIED	2026-10-14
7	7	Contractor submitted repair plan; verification inspection pending.	PENDING	2026-10-14
8	8	Affected section milled and resurfaced; compaction and core samples scheduled for verification.	VERIFIED	2026-10-14
9	10	Contractor submitted repair plan; verification inspection pending.	PENDING	2026-10-14

Monitoring Records

Monitoring ID	Project ID	Monitoring Date	Road Condition	Remarks
1	1	2026-10-15	AVERAGE	Observe rutting and shoulder performance under freight loading.
2	2	2026-10-15	POOR	Coastal spray and stormwater drainage need follow-up checks.
3	3	2026-10-15	AVERAGE	Recheck drainage after heavy rainfall.
4	4	2026-10-15	GOOD	Routine monitoring; no significant distress recorded.
5	6	2026-10-15	AVERAGE	Monitor wheel-path deformation at freight junctions.
6	7	2026-10-15	AVERAGE	Check salt exposure and surface cracking during monsoon.
7	9	2026-10-15	POOR	Flood-prone section; inspect culverts and embankment after rain.
8	10	2026-10-15	AVERAGE	Track rutting in container lanes.
9	11	2026-10-15	GOOD	Joint condition and slab performance within expected range.
10	12	2026-10-15	POOR	Continue slope movement and erosion monitoring.
11	13	2026-10-15	AVERAGE	Monitor crack propagation and ride quality.

Risk Assessments

Assessment ID	Project ID	Material Score	Thickness Score	Defect Score	Traffic Load Score	Drainage Score	Risk Score	Risk Category	Coverage %	Recommended Premium INR	Assessed By
1	1	92	83	28	50	50	41.53	MEDIUM	80	72916880.0	5
2	2	74	79	40	81	58	36.96	MEDIUM	80	212151040.0	5

Assessment ID	Project ID	Material Score	Thickness Score	Defect Score	Traffic Load Score	Drainage Score	Risk Score	Risk Category	Coverage %	Recommended Premium INR	Assessed By
3	3	79	77	35	63	72	33.83	MEDIUM	80	11860128.0	5
4	4	65	72	61	69	63	38.58	MEDIUM	80	32349504.0	5
5	5	65	89	35	72	76	28.15	MEDIUM	80	21004880.0	5
6	6	85	70	44	49	55	44.58	MEDIUM	80	21820288.0	5
7	7	71	76	42	78	79	31.38	MEDIUM	80	15605984.0	5
8	8	95	84	79	85	52	16.07	LOW	90	5552664.0	5
9	9	87	74	44	84	73	26.19	MEDIUM	80	18919824.0	5
10	10	94	87	52	54	69	25.92	MEDIUM	80	12872576.0	5
11	11	77	73	72	57	61	36.51	MEDIUM	80	28442224.0	5
12	12	89	72	37	69	77	36.0	MEDIUM	80	13859200.0	5
13	13	93	75	36	55	59	35.58	MEDIUM	80	9498944.0	5
14	14	75	73	63	80	59	27.46	MEDIUM	80	6043392.0	5
15	15	95	89	65	62	91	18.08	LOW	90	9167424.0	5

Policy Proposals

Proposal ID	Project ID	Material	Thickness	Defect	Traffic	Drainage	Risk Score	Risk Category	Coverage %	Premium INR	Status	Valid Until	Assessed By	
1	1	92	83	28	50	50	41.53	MEDIUM	80	72916880.0	5	PENDING	2027-10-31	5
2	2	74	79	40	81	58	36.96	MEDIUM	80	212151040.0	5	PENDING	2027-10-31	5
3	3	79	77	35	63	72	33.83	MEDIUM	80	11860128.0	5	PENDING	2027-10-31	5
4	4	65	72	61	69	63	38.58	MEDIUM	80	32349504.0	5	ACCEPTED	2027-10-31	5
5	5	65	89	35	72	76	28.15	MEDIUM	80	21004880.0	5	PENDING	2027-10-31	5
6	6	85	70	44	49	55	44.58	MEDIUM	80	21820288.0	5	PENDING	2027-10-31	5
7	7	71	76	42	78	79	31.38	MEDIUM	80	15605984.0	5	PENDING	2027-10-31	5
8	8	95	84	79	85	52	16.07	LOW	90	5552664.0	5	ACCEPTED	2027-10-31	5
9	9	87	74	44	84	73	26.19	MEDIUM	80	18919824.0	5	PENDING	2027-10-31	5
10	10	94	87	52	54	69	25.92	MEDIUM	80	12872576.0	5	PENDING	2027-10-31	5
11	11	77	73	72	57	61	36.51	MEDIUM	80	28442224.0	5	ACCEPTED	2027-10-31	5
12	12	89	72	37	69	77	36.0	MEDIUM	80	13859200.0	5	PENDING	2027-10-31	5
13	13	93	75	36	55	59	35.58	MEDIUM	80	9498944.0	5	PENDING	2027-10-31	5
14	14	75	73	63	80	59	27.46	MEDIUM	80	6043392.0	5	PENDING	2027-10-31	5
15	15	95	89	65	62	91	18.08	LOW	90	9167424.0	5	PENDING	2027-10-31	5

Policies

Policy ID	Project ID	Proposal ID	Policy Number	Premium INR	Coverage %	Status	Issue Date	Expiry Date	Issued By
1	4	4	RS-IND-2026-0004	5	32349504.0	ACTIVE	2026-10-01	2027-10-01	5
2	8	8	RS-IND-2026-0008	5	5552664.0	ACTIVE	2026-10-01	2027-10-01	5
3	11	11	RS-IND-2026-0011	5	28442224.0	ACTIVE	2026-10-01	2027-10-01	5

Claims

Claim ID	Project ID	Policy ID	Claim Reason	Estimated Repair Cost INR	Claim Status	Raised By	Rejection Reason
1	4	1	Potholes and surface deformation reported after prolonged rainfall	18500000	SETTLED	2	—
2	8	2	Cracking near utility reinstatement and junction turning area	7400000	REJECTED	9	Damage was outside the covered period after review of policy dates.
3	11	3	Concrete slab distress and joint damage following heavy vehicle loading	12600000	UNDER_ASSESSMENT	2	—

Claim Assessments

Assessment ID	Claim ID	Adjuster ID	Severity	Damage %	Damage Category	Policy Violation	Site Inspection	Assessment Notes	Recommended Settlement INR	Assessment Status
1	1	6	MODERATE	28	POTHOLE	FALSE	TRUE	Site inspection found localised potholes and surface deformation; policy coverage checked; no material policy violation identified.	5200000	COMPLETED
2	2	6	MINOR	12	CRACK	TRUE	TRUE	Inspection found cracking near a utility reinstatement. Policy-period exclusion applied; rejection recommended.	0	REJECTED
3	3	6	MAJOR	46	STRUCTURAL_DAMAGE	FALSE	TRUE	Joint and slab distress requires additional core testing and engineering review; preliminary settlement recommendation only.	8900000	PENDING

Settlements

Settlement ID	Claim ID	Settlement Amount INR	Payment Status	Approved By
1	1	5200000	PAID	6
2	2	0	NOT_PAYABLE	6

Payments

Payment ID	Policy ID	Amount INR	Payment Type	Payment Status	Payment Date
1	1	5	PREMIUM	SUCCESS	2026-10-01
2	2	5	PREMIUM	SUCCESS	2026-10-01
3	3	5	PREMIUM	SUCCESS	2026-10-01
4	1	5200000	SETTLEMENT	SUCCESS	2026-10-18

Notifications

Notification ID	User ID	Title	Message	Is Read	Created At
1	2	Project Created	Project record created and assigned for construction planning.	TRUE	2026-10-06 10:07:00
2	3	Construction Details Submitted	Construction methodology and materials were submitted for review.	FALSE	2026-10-07 10:14:00
3	4	Inspection Created	A new site inspection record is available.	FALSE	2026-10-08 10:21:00
4	2	Inspection Rejected	Inspection did not meet acceptance criteria; corrective work is required.	TRUE	2026-10-09 10:28:00
5	3	Corrective Action Submitted	Contractor submitted corrective action for verification.	FALSE	2026-10-10 10:35:00
6	4	Corrective Action Verified	Corrective action verification was completed.	FALSE	2026-10-11 10:42:00
7	5	Risk Assessment Created	Risk assessment completed; review scores and recommended coverage.	FALSE	2026-10-12 10:49:00
8	5	Policy Proposal Generated	Insurance proposal generated and is awaiting decision.	FALSE	2026-10-13 10:56:00
9	2	Claim Submitted	A road damage claim was submitted for assessment.	TRUE	2026-10-14 10:03:00
10	6	Claim Assessed	Claim assessment notes and settlement recommendation were saved.	FALSE	2026-10-15 10:10:00
11	2	Settlement Paid	Settlement payment was processed successfully.	TRUE	2026-10-16 10:17:00

Workflow Reference

Role	Typical Flow
Road Authority PM	Create project and assign authority/contractor details; project advances through configured status values.
Contractor PM	Submit construction details and record progress milestones with percentage and work description.
Inspector	Record initial, periodic and final inspections; enter material quality, layer thickness and test scores; pass/fail and approve/reject as appropriate.
Contractor PM + Inspector	Link defects to failed inspections; submit corrective actions; verify them and perform follow-up inspections.
Underwriter	Retrieve project history, inspection failures, defects, repairs, monitoring, and risk factors; prepare risk assessment, coverage and premium proposal.
Claims Adjuster	Retrieve claim; inspect site; record damage category and percentage; check policy violations; determine severity; recommend settlement; approve or reject with reasons and trigger notifications.

Retrieval Notes

All project, organization, user, inspection, defect, risk, policy, claim, payment and notification records in this revised knowledge base are coherent synthetic demo data designed to resemble populated application tables. They are not claims of verified real-world projects or insurer decisions. Locations include India and international examples. Use them to test retrieval and workflows; validate real outcomes before using data for actuarial or operational predictions.

The score values and recommended premiums are example values for testing only. No production risk-score or premium formula was supplied. The GPT should explain uncertainty, cite the relevant project and inspection IDs, and distinguish retrieved records from its own estimate.