Insurance Claim Help

Report

Damage and Expense Report

A simple overview of room damages, repair costs, and supporting claim media.

ROOM **#128**	**REFERENCE** **RPT-893392DF05**
STATUS **Created**	**TOTAL COST** **£1,365.00**
REPAIR ITEMS **7**	**ESTIMATED COMPLETION** **2026-04-04 15:31:02.548217+00:00**

Property Details

PROPERTY ID
7

ADDRESS
House 14, Baneshwor, Kathmandu

TYPE
Residential

POSTCODE
44600

Homeowner Details

NAME
Nischal Shrestha

ROLE
Homeowner

EMAIL
nischal@gmail.com

CONTACT
9865122342

DAMAGE ASSESSMENT

Type	Location	Severity
large hole	ceiling	High
extensive peeling paint/plaster	walls and ceiling	High
water stains	walls	High
cracks	ceiling	Medium
debris (rubble)	floor	High
broken floor tiles	floor	Medium
peeling paint	door frames	Medium

REPAIR ITEMS

ID	Material	Quantity	Cost
95	Wood Stud	5	£50.00
96	Plaster	10	£500.00
97	Primer	5	£150.00
98	Interior Paint	10	£300.00
99	Ceramic Tile	100	£250.00
100	Thinset Mortar	3	£75.00
101	Grout	2	£40.00

MEDIA

Media #128