

Inspection: Line Inspection — Cotobie <> Addis East I — Cotobie <> Addis East I 132 kV

Checklist	Line Hardware & Fittings · CL-WB-HW-INSP-A · v1
Task	TK-2026-000112 · Line Inspection — Cotobie <> Addis East I
Crew	Central 1 Transmission Line & OPGW Crew (CREW-C1-TLOM)
Executed by	Fikadu Bekele
Started	09/28/2026, 07:13 PM
Submitted	09/28/2026, 07:13 PM
Result	FAIL
Steps passed	3 of 4 · 1 critical failed
Notes	—

WORK LOCATION DETAIL

Region	Central 1 Region Transmission Substation Operation
Transmission line	Cotobie <> Addis East I · TL-C1-0012
Line route	COTOBIE II → ADDIS EAST I
Line rating	132 kV · OVERHEAD · 5.6 km · ACCR

ROUTE MAP



Cotobie <> Addis East I — 132 kV · OVERHEAD · 5.6 km
COTOBIE II → ADDIS EAST I

Dispatch note — missed items

Missed certification	SWITCHING_AUTHORITY, HEIGHT_WORK, TOWER_CLIMBING, FIRST_AID
Team shortfall	3 person(s)

RECOMMENDED EQUIPMENT FOR THIS JOB

USED Binoculars	USED camera	USED Thermal camera
USED Washing equipment	USED water	USED Replacement discs
USED tools	USED Pollution measurement kit	USED Crack gauge
USED level	USED measuring tape	USED Grout
USED protective coating	USED checklist	USED Torque wrench
USED spanner set	USED Rust meter	USED visual

- USED

OTDR test set
- USED

Chainsaw
- USED

Vibration recorder
- USED

Earth tester
- USED

sealing kit
- USED

brush cutter
- USED

Ground rods
- USED

GPS receiver
- USED

Laser distance meter
- USED

Replacement members
- USED

conductors
- USED

Visual walk-around

Checked equipment is recorded as used; unchecked recommendations are reported as missed.

WORKFLOW

Created by

Abrham Workie

Assigned by

Abrham Workie

Executed by

Fikadu Bekele

Verified by

Dereje Gezahagn

Central 1 Transmission Line & OPGW Crew executed Line Hardware & Fittings on Line Cotobie <> Addis East I (TL-C1-0012) — field worker Fikadu Bekele, recording 4 step(s). 1 critical step(s) failed — a corrective follow-up is recommended.

Checklist steps executed on site

Seq	Section	Step	Response recorded	Assessment	Comment
1	Visual	Are all vibration dampers present and undamaged?	Yes	Passed	—
2	Visual	Are all spacers present and undamaged?	Yes	Passed	—
3	Visual	Are all grading rings present and undamaged?	Yes	Passed	—
4	GPS	CRIT · Capture the GPS position of the inspected Line Hardware & Fittings	9.004715, 38.810444 · ±106m	Failed	—