



Go to IoTLogIQ

Environmental Safety Monitoring Report

Report Date:	November 7, 2025
Report Time:	9:55:04 AM (Mexico Local Time)
Report Type:	Noon Shift Report

Executive Summary

Overall Status:	Safe
Badge Assignment:	107/136

Weather Station

Parameter	Value	Status
Temperature	26.3°C	Hot
Humidity	80.5%	High
Wind Speed	4 m/s	Breeze
Wind Direction	38.4°	West
Pressure	1013.3 hPa	Stable
Rainfall	0.05 mm	Dry

H2S Sensor Monitoring

Location	Current Level (ppm)	Status
DOCK 4 AND 5	0.1 ppm	Safe
PIPE YARD	0.00033 ppm	Safe
PARKING ZONE	0.2 ppm	Safe
DOCK 3	0.21 ppm	Safe

■ 24-Hour Historical Summary

Location	Min (ppm)	Max (ppm)	Avg (ppm)
DOCK 4 AND 5	0.09 ppm	0.1 ppm	0.1 ppm
PIPE YARD	0.00005 ppm	0.06115 ppm	0.008 ppm
PARKING ZONE	0.19 ppm	0.2 ppm	0.198 ppm
DOCK 3	0.21 ppm	0.21 ppm	0.21 ppm