

WETT Level 1 Visual Inspection Report

Wood-Burning Appliance Condition Record

Report Number	WETT-2026-0730	Inspection Date	July 23, 2026
Property Owner	John Maschak	Site Address	27 Cedar Ridge Road, Port Hardy, BC V0N 2P0
Inspector	Morgan Patel	WETT Certification No.	7180
Company	North Coast Hearth Safety	Requested By	Mini Home Energy Solutions

Purpose and Scope

A Level 1 visual inspection was completed to document the existing freestanding wood stove and visible venting before its removal as part of a wood-to-air-source-heat-pump conversion. The inspection was based on readily accessible visible conditions at the site on the inspection date.

Appliance and Venting Identification

Appliance Type	Freestanding, manually fuelled wood stove
Fuel	Seasoned cordwood / solid fuel
Location	Main-floor living room, exterior-wall installation
Visible Connector	Single-wall black steel connector, approximately 150 mm / 6 in. diameter
Chimney System	Factory-built insulated chimney through ceiling and roof
Data Plate	Present and legible at time of inspection

Level 1 Visual Inspection Observations

Inspection Item	Observed Condition	Result
General appliance condition	Door, latch, glass, firebox, and exterior surfaces visually intact with normal signs of wear.	Observed
Floor protection	Non-combustible hearth pad present beneath and in front of appliance.	Observed
Connector condition	Visible connector sections secured; no visible perforation or heavy corrosion noted.	Observed
Clearance context	Surrounding wall, floor, and nearby area photographed before appliance removal.	Recorded
Smoke / CO alarms	Alarms observed in the dwelling during site visit.	Observed

Removal and Upgrade Record

Removal Contractor	Mini Home Energy Solutions, Victoria, BC
Removal Date	July 25, 2026
Wood Appliance Disposition	Disconnected, removed from the home, and transported for recycling.
Interior Completion	Connector and visible wall collar removed; interior wall penetration and floor area professionally finished.
Replacement Primary System	TOSOT cold-climate air-source heat pump, outdoor unit TU36-24WADU with indoor unit TUD36-24AH2ADU.
Related Invoice	Mini Home Energy Solutions invoice MES-20260730-003, issued July 30, 2026.

Conclusion

The freestanding wood stove and visible connector were present at the installation site on July 23, 2026 and were documented before removal. The inspection record, contractor invoice, and matched before-and-after photographs support that the former wood-burning appliance was removed as part of the heat pump conversion.

Attachments referenced: 02_Before_Wood_Heating_System.jpg; 03_After_Heat_Pump_Installation.jpg;
01_Mini_Home_Energy_Solutions_Invoice.pdf

Morgan Patel, WETT Certified Professional 7180

North Coast Hearth Safety