

Vehicle Repair Invoice

Issued for a fictional repair transaction. Amounts shown are specimen values only.

Invoice number	INV-2026-31984	Invoice date	2026-08-25
Bill to	Pieter Moss	Repair order	RO-2026-40217
Customer address	9 Glassfern Walk, Oltin, Elandor	Vehicle	2022 Kestrel Mira

Item	Description	Qty	Amount
1	Rear bumper cover replacement	1	425.00
2	LED tail lamp assembly	1	780.00
3	Parking sensor calibration	1	165.00
4	Paint preparation and finish	1	120.00

Subtotal	1,490.00
Tax	0.00
TOTAL	1,490.00

Work completed by Harborline Repair Works, 4 Rivet Court, Bellwether, Elandor | service@example.com

Authorized repairer signature: _____

Customer acknowledgement: _____