lyft | ALABAMA

ASE VEHICLE INSPECTION

LYFT DRIVER INFO

ALL FIELDS ARE MANDATORY

Deyvis Ulloa
LYFT DRIVER NAME

xavier.dey2610@gmail.com
EMAIL ADDRESS

44CWE0C
LICENSE PLATE #

5NPD84LF9HH185763
VIN

HYUNDAI
VEHICLE MAKE

Elantra
VEHICLE MODEL

2017
VEHICLE YEAR

LYFT DRIVER SIGNATURE

+17706247821
LYFT DRIVER PHONE NUMBER

ASE VEHICLE INSPECTION CHECKLIST

	INSPECTION POINT	PASS	FAIL
1.	**Foot brakes**	☑	☐
2.	**Emergency brake (parking brake)**	☑	☐
3.	**Steering mechanism**	☑	☐
4.	**Windshield**	☑	☐
5.	**Rear window and other glass**	☑	☐
6.	**Windshield wipers**	☑	☐
7.	**Headlights**	☑	☐
8.	**Tail lights**	☑	☐
9.	**Turn indicator lights**	☑	☐
10.	**Stop lights**	☑	☐
11.	**Front seat adjustment**	☑	☐
12.	**Doors (open, close, unlock)**	☑	☐
13.	**Horn**	☑	☐
14.	**Speedometer**	☑	☐
15.	**Bumpers**	☑	☐
16.	**Muffler and exhaust system**	☑	☐
17.	**Tires, incl. tread depth**	☑	☐
	Left front	☑	☐
	Right front	☑	☐
	Left rear	☑	☐
	Right rear	☑	☐
18.	**Interior and exterior rear view mirrors**	☑	☐
19.	**Safety belts and air bags for driver and passenger(s)**	☑	☐
20.	**AC/Heat**	☑	☐

VEHICLE INSPECTION (Circle One) **PASS** **FAIL**

TO BE COMPLETED BY INSPECTOR

Note: This inspection shall be performed by an American Advanced Technicians Institute (AATI) certified mechanic or a National Institute for Automotive Service Excellence (ASE) certified mechanic or by a mechanic that is under the supervision of an AATI or ASE certified mechanic.

Car Care Center
COMPANY NAME

John Grey
INSPECTOR NAME

3417 J st
COMPANY/FACILITY ADDRESS

08/30/2026
INSPECTION DATE (document expires one year from this date)

171796
VEHICLE MILEAGE

ASE-6057-9283
AATI/ASE CERTIFICATION NO.

John
INSPECTOR SIGNATURE

NAME OF SUPERVISING AATI OR ASE CERTIFIED MECHANIC (IF DIFFERENT FROM ABOVE)