lyft | CALIFORNIA

VEHICLE INSPECTION

LYFT DRIVER INFO

ALL FIELDS ARE MANDATORY

Brittany Gonzalez
LYFT DRIVER NAME

+15107068740
LYFT DRIVER PHONE NUMBER

9LQJ169
LICENSE PLATE #

JTDBCMFE2RJ028948
VIN

TOYOTA
VEHICLE MAKE

Corolla
VEHICLE MODEL

2024
VEHICLE YEAR

LYFT DRIVER SIGNATURE

VEHICLE INSPECTION CHECKLIST

	INSPECTION POINT	PASS	FAIL
1.	**Foot brakes**	☑	☐
2.	**Emergency brake (parking brake)**	☑	☐
3.	**Steering mechanism**	☑	☐
4.	**Windshield**	☑	☐
5.	**Rear window and other glass**	☑	☐
6.	**Windshield wipers**	☑	☐
7.	**Headlights**	☑	☐
8.	**Tail lights**	☑	☐
9.	**Turn indicator lights**	☑	☐
10.	**Stop lights**	☑	☐
11.	**Front seat adjustment**	☑	☐
12.	**Doors (open, close, lock)**	☑	☐
13.	**Horn**	☑	☐
14.	**Speedometer**	☑	☐
15.	**Bumpers**	☑	☐
16.	**Muffler and exhaust system**	☑	☐
17.	**Tires, incl. tread depth**	☑	☐
	Left front	☑	☐
	Right front	☑	☐
	Left rear	☑	☐
	Right rear	☑	☐
18.	**Interior and exterior rear view mirrors**	☑	☐
19.	**Safety belts for driver and passenger(s)**	☑	☐

VEHICLE INSPECTION (Circle One) **PASS** **FAIL**

TO BE COMPLETED BY INSPECTOR

Mascot FC 9TIC812 Car Center
COMPANY NAME

John Grey
INSPECTOR NAME

3417 J st, Sacramento, CA 95816
COMPANY/FACILITY ADDRESS

09/03/2026
INSPECTION DATE (document expires one year from this date)

64118
VEHICLE MILEAGE

ARD315746
ARD NUMBER

John
INSPECTOR SIGNATURE

Applicants who do not match the photo on their driver's license or do not have the proper documents, cannot complete an inspection. Failing inspections can only be remedied by the same shop on the same day. If an applicant fails the inspection and is unable to fix the issues on the spot, a new appointment must be made, and a new inspection form must be used.

This inspection form reflects a 19 point inspection only on the date of the inspection listed above. For purposes of this inspection, the wheels were not removed from the vehicle, and the vehicle was not put on a lift, nor was it checked for emissions.

Repair Estimate

INSVE Vehicle Inspections

Customer information

- **Name:** Brittany Gonzalez
- **Phone number:** +15107068740
- **Email:** paigeg@lyft.com

Vehicle information

- **License plate №:** 9LQJ169
- **VIN:** JTDBCMFE2RJ028948
- **Make:** TOYOTA
- **Model:** Corolla
- **Year:** 2024
- **Odometer:** 64118

Repair details

Description	Quantity	Unit Price ($)	Total Price ($)
Vehicle inspection	1	*	*
Total:			*

Additional notes

*** Prices vary depending on the number of inspection companies chosen by the customer. Final cost will be confirmed at checkout.**

Date: 09/03/2026