TURO

Annual vehicle inspection checklist

INSPECTION POINT	PASS	FAIL
1 Brakes — shoes & pads (≥3mm thick)	☑	☐
2 Emergency brake (parking brake)	☑	☐
3 Steering mechanism	☑	☐
4 Windshield	☑	☐
Large crack (Greater than 1") = Fail		
Small crack (Smaller than 1") = Pass		
5 Rear window and other glass	☑	☐
6 Windshield wipers	☑	☐
7 Headlights and tail lights	☑	☐
8 Turn indicator lights	☑	☐
9 Brake lights	☑	☐
10 Front seat adjustment	☑	☐
11 Doors (open, close, lock)	☑	☐
12 Horn	☑	☐

INSPECTION POINT	PASS	FAIL	
13 Speedometer and warning lights	☑	☐	
14 Bumpers	☑	☐	
15 Muffler and exhaust system	☑	☐	
16 Is the manufacture date for the tires less than 6 years old?	☑	☐	
17 Tires incl. tread depth (4/32" required)	☑	☐	
Right front measurement			6/32
Left front measurement			6/32
Right rear measurement			7/32
Left rear measurement			7/32
18 Interior and exterior rear view mirrors	☑	☐	
19 Seat belts for driver and passenger(s)	☑	☐	
20 Is the battery less than 5 years old?	☑	☐	
21 If the battery is more than 5 years old, is the voltage greater than 12.1V using a multimeter?	☑	☐	

VEHICLE INSPECTION (please circle) — PASS / FAIL

Anthony Fontaine
HOST NAME

anthonyfontaine25@gmail.com
HOST EMAIL ADDRESS

Anthony Fontaine
HOST SIGNATURE

+13864500160
HOST PHONE NUMBER

09/03/2026
DATE

TO BE COMPLETED BY QUALIFIED MECHANIC

RAWP82
LICENSE PLATE #

JM1DEIKZ9E0171874
VIN #

154230
VEHICLE MILEAGE

MAZDA
VEHICLE MAKE

Mazda2
VEHICLE MODEL

2014
VEHICLE YEAR

INSVE Vehicle Inspections, 3417 J St, Sacramento, CA 95816
INSPECTOR COMPANY AND ADDRESS

ARD315746
LICENSE/ASE ID # (OPTIONAL)

John Grey
INSPECTOR NAME

John
INSPECTOR SIGNATURE

09/03/2026
DATE

TURO HOSTS: PLEASE ENSURE ALL FIELDS ON THIS CHECKLIST ARE COMPLETED AND THAT YOUR CAR PASSED THE INSPECTION BEFORE SUBMITTING IT IN YOUR CAR'S "SAFETY INSPECTIONS" TAB.

Repair Estimate

INSVE Vehicle Inspections

Customer information

- **Name:** Anthony Fontaine
- **Phone number:** +13864500160
- **Email:** anthonyfontaine25@gmail.com

Vehicle information

- **License plate №:** RAWP82
- **VIN:** JM1DE1KZ9E0171874
- **Make:** MAZDA
- **Model:** Mazda2
- **Year:** 2014
- **Odometer:** 154230

Repair details

Description	Quantity	Unit Price ($)	Total Price ($)
Vehicle inspection	1	*	*
Total:			*

Additional notes

*** Prices vary depending on the number of inspection companies chosen by the customer. Final cost will be confirmed at checkout.**

Date: 09/03/2026