AI Visual Quality Inspection Report

A factual record of the stored organizer-model result and any supervisor review.

REPORT REFERENCE	INSPECTION ID	REPORT STATUS
MQS-IR-13-20261102230819	#13	Completed
GENERATED	BATCH ID	PRODUCT
2026-11-02 23:08:19 UTC	#9	P-PLATE01

Executive summary

NORMAL

Predicted classification	Normal
Model confidence	97.80%
Defect probability	2.20%
Product identifier	P-PLATE01
Model version	BIT-PLATE-CV-1.0
Completion status	Completed

Inspection information

Inspection ID	#13
Batch ID	#9
Product	P-PLATE01 - Demonstration metal plate
Original filename	inspection_008.jpg
Submitted by	engineer_demo
Submitted at	2026-11-02 23:02:07 UTC
Completed at	2026-11-02 23:02:07 UTC
Inspection status	Completed
Model version	BIT-PLATE-CV-1.0

Image evidence

File: inspection_008.jpg | Format: JPEG | Dimensions: 256 x 256 px | Size: 4.1 KiB



AI classification results

Predicted class	Normal
Model confidence	97.80%
Defect probability	2.20%
Raw defect probability	0.021991
Decision threshold	0.50
Decision rule	Defective when defect probability >= 0.50; Normal when defect probability < 0.50.
Model version	BIT-PLATE-CV-1.0

Confidence is the model score for the predicted class. Defect probability is the separate raw score used by the decision threshold.

Processing details

Submission time	2026-11-02 23:02:07 UTC
Processing start	2026-11-02 23:02:07 UTC
Completion time	2026-11-02 23:02:07 UTC
Processing duration	0.03 seconds
Processing status	Completed
Failure reason	-

Supervisor review

Awaiting Supervisor Review.

Technical information

Supplied classifier type	Standardized 17-dimensional image features and logistic regression
Inference method	Supplied Model/inference.py predict helper, called with the saved inspection image.
Model version	BIT-PLATE-CV-1.0
Decision threshold	0.50
Image processing details	RGB image; exact pipeline in inference.py
Verified limitations	Synthetic, fixed framing only. Uncalibrated scores. No real factory validity.

Conclusion

The stored model result for inspection #13 is Normal. No supervisor review has been recorded.

Disclaimer

The model confidence and defect probability are uncalibrated model scores and should not be interpreted as verified probabilities of product safety or real-world manufacturing quality. The supplied model was evaluated on synthetic organiser-provided images. Performance on real-world manufacturing images has not been established by this evaluation.