

Service Report



Report Number : C139-94102-S2-01-R1
Client Name : Morrison Test
Company : test
Service Address : Test Address
San Francisco, California
94102
Purpose Of Visit : Maintenance Services
Service Date : 07/13/2017
Technician : IBCnet Support Empl
Work Performed : Performed
Recommendations for customer : NA

Unit Serviced

| Unit Name |
|----------------------|
| AC1 Residential Plan |
| AC2 Residential Plan |

Material Used

| SR | Part | Qty |
|----|-----------------------------------|-----|
| 1 | Refrigerant 410A - 1lbs | 1 |
| 2 | HARD START KIT FCSRU2 - 3-1/2 TON | 1 |
| 3 | AUTO FUSES DIV626AT0003 - 3 AMP | 1 |
| 4 | Filter Kit - Filter Kit 10 | 1 |
| 5 | COIL CLEANER N417175 - 1 | 1 |
| 6 | Emergency Fee - | 1 |
| 7 | Refrigerant 410A - 1lbs | 1 |
| 8 | HARD START KIT FCSRU2 - 3-1/2 TON | 1 |
| 9 | AUTO FUSES DIV626AT0003 - 3 AMP | 1 |
| 10 | Filter Kit - Filter Kit 10 | 1 |
| 11 | COIL CLEANER N417175 - 1 | 1 |
| 12 | Emergency Fee - | 1 |

Part Requested

| SR | Part | Qty |
|----|------|-----|
| NA | | |

Report Image



You acknowledge that the unit(s) listed are covered by the Plan Services as described in our agreement, that each unit was personally examined by you and that the unit(s) is/are in good and serviceable condition and that equipment described (hereinafter referred to as the "Equipment") comprised the entirety of the unit.

