

INSPECTION REPORT FOR WORK DETAILS OF HDD MACHINE



HORIZONTAL DIRECTIONAL DRILLING

24/278, 1st Floor, ALFAS COMPLEX, Cochin University Road
South Kalamassery, Kochi-682022, GSTIN: 32BDIPS2962R2ZS
Ph: 9747044117, Email: horizontaldirectionaldrilling@gmail.com

No.

1725

Client		Route		Site Location		Report No	
Vendor Name		Tracker Name		Operator Name		Date	
Machine No/Name		Shot Length (M)		Srala Details		Rod Length (M)	
No. of Duct/Color		Duct Length (M)		Job No.		Pitch	
Entry Pit GPS Cord. Latitude/Longitude		Exit Pit GPS Cord. Latitude/Longitude		Scale: X axis= 3		Scale: Y axis= 1	
Rod		Pitch		Depth		Rod	
1		-30		1.80		26	
2		-10		1.60		27	
3		-8		2.10		28	
4		-7		2.40		29	
5		-8		2.50		30	
6		-2		2.60		31	
7		-2		2.70		32	
8		40		2.80		33	
9		40		2.90		34	
10		43		2.80		35	
11		42		2.70		36	
12		40		2.60		37	
13		40		2.50		38	
14		40		2.40		39	
15		43		2.40		40	
16		40		2.40		41	
17		40		2.40		42	
18		40		2.40		43	
19		-3		2.80		44	
20		-3		2.60		45	
21		-7		2.60		46	
22		40		2.85		47	
23		43		2.80		48	
24		43		2.80		49	
25		40		2.45		50	

Y 6 9 12 15 18 21 24 27 30 33 36 39 42 45 48 51 54 57 60 63 66 69 72 75 78 81

Scale: X axis= 3

Scale: Y axis= 1

OFFSET DRAWING

Contractor Representative

Filed Engineer

Signature

Name

Date

**HORIZONTAL
DIRECTIONAL
DRILLING**

24/278, 1st Floor, ALFAS COMPLEX, Cochin University Road
South Kalamassery, Kochi-682022, GSTIN: 32BDIPS2962RZS
Ph: 9747044117, Email: horizontaldirectional05@gmail.com

No. 1726

[illegible]

No. 1747



