

Firmware Analysis Report

Project: Relion670_Firmware update 1p1r01 to 27.zip
Architecture: Unknown
File Size: 13681652 bytes
SHA256: 5ee59011bda064e1fe19da62e28c39188fe6be8e9812f7ff7aaedc199be3723f

Executive Summary

This report was automatically generated by the FAWS system. It contains the results of a multi-stage static, dynamic, and symbolic firmware analysis.

Analysis Stages

Tool: BINWALK

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\venv\Scripts\python.exe" tools/binwalk.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\36_Relion670_Firmware update 1p1r01 to 27.zip" --project "36" --run-id 0

Analyzed successfully, found 2 findings.
Analyzed successfully, found 2 findings.
Analyzed successfully, found 2 findings.

Tool: STRINGS

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\venv\Scripts\python.exe" tools/strings.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\36_Relion670_Firmware update 1p1r01 to 27.zip" --project "36" --run-id 0

Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.

Tool: ENTROPY

Status: SUCCESS | Command: "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\venv\Scripts\python.exe" tools/entropy.py --target "C:\Users\akars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\36_Relion670_Firmware update 1p1r01 to 27.zip" --project "36" --run-id 0

Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.

Tool: YARA

Status: SUCCESS | Command: echo 'Tool yara not configured'

Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.

Tool: SYMBOL_ANALYSIS

Status: SUCCESS | Command: echo 'Tool symbol_analysis not configured'

Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.
Analyzed successfully, found 0 findings.

Tool: SCORECARD

Status: SUCCESS | Command: "C:\Users\lakars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/scorecard.py --target "C:\Users\lakars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\36_Relion670_Firmware update 1p1r01 to 27.zip" --project "36" --run-id 0

Starting Risk Scorecard Generation on project 36... Found 1 finding(s). [!] RiskScore:
Calculated Aggregate Risk Score: 100/100 based on 0 findings Scan complete.
Starting Risk Scorecard Generation on project 36... Found 1 finding(s). [!] RiskScore:
Calculated Aggregate Risk Score: 98/100 based on 1 findings Scan complete.
Starting Risk Scorecard Generation on project 36... Found 1 finding(s). [!] RiskScore:
Calculated Aggregate Risk Score: 96/100 based on 2 findings Scan complete.

Tool: PDF_REPORT

Status: RUNNING | Command: "C:\Users\lakars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\.venv\Scripts\python.exe" tools/pdf_report.py --target "C:\Users\lakars\OneDrive\Desktop\Firmware Analysis workflow simulator\backend\data\uploads\36_Relion670_Firmware update 1p1r01 to 27.zip" --project "36" --run-id 0

Starting PDF Report Generation on project 36... Generated PDF report at
data/artifacts\FAWS_Report_36.pdf PDF generation successful. Report generation complete.
Starting PDF Report Generation on project 36... Generated PDF report at
data/artifacts\FAWS_Report_36.pdf PDF generation successful. Report generation complete.